

2026 AEA Convention & Trade Show



March 23-26, 2026



Regulatory Rise & Shine

Ric Peri

Aircraft Electronics Association

ricp@aea.net

202-589-1144



From the FAA

- **Inspection Programs for Single-Engine Turbine-Powered Airplanes and Unmanned Aircraft; Miscellaneous Maintenance-Related Updates**
 - Directly affecting repair stations by proposing to amend:
 - 14 CFR 145.109 by removing the last sentence and its prescriptive list of documents in §145.109(d).
 - §§145.201(a)(2) and 145.217 (Contract Maintenance),
 - Currently at DOT awaiting signature.



§ 145.109 Equipment, materials, and data requirements.

- (d) A certificated repair station must maintain, in a format acceptable to the FAA, the documents and data required for the performance of maintenance, preventive maintenance, or alterations under its repair station certificate and operations specifications in accordance with part 43. The following documents and data must be current and accessible when the relevant work is being done:
 - (1) Airworthiness directives,
 - (2) Instructions for continued airworthiness,
 - (3) Maintenance manuals,
 - (4) Overhaul manuals,
 - (5) Standard practice manuals,
 - (6) Service bulletins, and
 - (7) Other applicable data acceptable to or approved by the FAA.



We Ask – FAA Answers


- New part 43 (43.3/43.7) proposal being processed:
 - Mutual Acceptance of Maintenance



We Ask – FAA Answers

We [FAA] conclude that the CAET certification program provides current, comprehensive, and rigorous assessments, and is an acceptable AMOC.

As such, it meets the intent of the regulatory requirements outlined in 14 CFR § 65.101(a)(5)(ii) for the issuance of a repairman's certificate.



- When testing ADS-B please validate that you are using the prescribed RF shielding equipment to prevent HMI (Hazardously Misleading Information) events at your repair station/airport.
- The ADS-B Focus Team (AFT) refers to these as Ramp Test Events and are checked daily by an Inspector with the AFT. Most of these events are caused by not following the Aircrafts Maintenance Manual. The AFT also see “escapes” caused by improper use of the transponder antenna shields or RF Blankets. Refer to the Safety Alert for Operators (SAFO) 17002, “Improper Transponder and Automatic Dependent Surveillance-Broadcast (ADS-B) OUT Equipment Testing”.



- When repairing/replacing ADS-B components please request a Public ADS-B Performance Report (PAPR) as your final confirmation that the system is operating appropriately as required.
- When replacing a transponder, make sure the transponder is programmed with the aircraft's correct N-number and corresponding ICAO address.



- The AFT highly recommends that IA mechanics request a Public ADS-B Performance Report (PAPR) before performing an Annual Inspection, to check the aircraft's ADS-B for compliance with §91.227.

- <https://adsbperformance.faa.gov/PAPRRequest.aspx>



- If an individual has trouble requesting a Public ADS-B Performance Report (PAPR), contact the ADS-B Focus Team at adsbfocusteam@faa.gov or 9-AWA-AFS-300-ADSB-AvionicsCheck (FAA) for assistance.



AC 43.13-1

- The Advisory Circular AC 43.13-1 is in the beginning stages of a rewrite affecting several chapters.
- An online format change will be changing the numbering and sequence of the topics; and the addition of one new topic.



Cockpit Voice Recorder (CVR)

- Per the FAA Reauthorization Act of 2024, Title III Aviation Safety Improvements, Section 366 - 25 HR Cockpit Voice Recorder (CVR), the Forward Fit (newly manufactured aircraft) has been released affecting 14 CFR Parts 91, 121, 125, 129 and 135 operators and the retrofit portion (existing aircraft) will be released in a subsequent rulemaking document.



25-Hour Cockpit Voice Recorder (CVR) Requirement, New Aircraft Production

- Final rule published February 2, 2026.
- This final rule increases the recording time of cockpit voice recorders (CVRs) from the currently mandated 2 hours to 25 hours for all affected future manufactured aircraft. This action provides accident investigators, aircraft operators, and civil aviation authorities with substantially more CVR data to help determine the probable causes of incidents and accidents and prevent future incidents and accidents. The action will also align the Federal Aviation Administration's (FAA) regulations more closely with existing international requirements.



§91.609 Flight data recorders and cockpit voice recorders.

- (i) (2) Retains at least—
 - (i) The last 25 hours of recorded information using a recorder that meets the standards of TSO–C123c, or later revision, if:
 - (A) Manufactured on or after May 16, 2025, for transport category aircraft type-certificated with 30 or more passenger seats, or
 - (B) Manufactured on or after February 2, 2027, for airplanes or rotorcraft with a maximum certified takeoff weight (MCTOW) of 59,525 pounds or more and type-certificated for 29 or fewer passenger seats; or
 - (C) Manufactured on or after February 2, 2029, for airplanes or rotorcraft with a maximum certified takeoff weight (MCTOW) of 59,524 pounds or less; or (ii) ...

(*** 14 CFR Part 91, 125, 135 ***)



Cockpit Voice Recorder (CVR) - retroactive

NOTE:

- Section 366 is a self-enacting statute per the FAA Reauthorization Act of 2024 (law), so operators are required to still meet those requirements of 366.
(<https://www.govinfo.gov/content/pkg/PLAW-118publ63/pdf/PLAW-118publ63.pdf>)



SEC. 366. 25-HOUR COCKPIT VOICE RECORDER.

- (a) IN GENERAL
 - (2) COCKPIT VOICE RECORDER FOR COVERED AIRCRAFT.— Not later than 6 years after the date of enactment of this Act, a covered operator may not operate a covered aircraft unless such aircraft has a cockpit voice recorder installed that retains the last 25 hours of recorded information using a recorder that meets the standards of Technical Standard Order TSO–C123c, or any later revision.



SEC. 366. 25-HOUR COCKPIT VOICE RECORDER.

- (f) DEFINITIONS.—In this section:
 - (1) COVERED AIRCRAFT.—The term “covered aircraft” means—
 - (A) an aircraft operated by an air carrier under part 121 of title 14, Code of Federal Regulations; or
 - (B) a transport category aircraft designed for operations by an air carrier or foreign air carrier type-certificated with a passenger seating capacity of 30 or more or an all-cargo or combi derivative of such an aircraft.



GPS repeaters

- FAA is seeing the use of GPS repeaters inappropriately, if you are operating one you should have an FCC license, if you do not, and are using it, you should deactivate and secure it.
- The use of a GPS repeater inappropriately is an enforceable event from both the FAA and the FCC.



GPS repeaters

- Federal law prohibits the operation, marketing, or sale of any type of jamming equipment that interferes with authorized radio communications, including cellular and Personal Communication Services (PCS), police radar, and Global Positioning Systems (GPS).



GPS repeaters

- The following statement is from a supplier:
 - U.S. commercial customers must provide proof of authorization from the FCC. U.S. Government and military users must provide proof of authorization from the NTIA. Authorization/licensing needs to be obtained before purchase. For further information regarding NTIA requirements, see Chapter 8.3.28 of the NTIA manual. For further information regarding NTIA requirements, see: <https://apps.fcc.gov/coresWeb/publicHome.do>



GPS repeaters

- Additional from a supplier:
 - Current GPS Re-Radiating Kit Regulatory Concerns The regulatory policy that is currently in effect allows GPS Re-Radiating Kits to be sold to the following:
 - International Customers (outside the U.S.)
 - Agencies of the US Federal Government --All Branches of the US Military --Parties Operating under the Direction of US Federal Government
 - Parties that have received an STA or Experimental License under part 5 of the FCC rules
 - Parties that will be operating GPS Re-Radiators in a shielded room or under an approved GPS Networking Re-Radiating Hood



GPS repeaters

- FAA is seeing the use of GPS repeaters inappropriately, if you are operating one you should have an FCC license, if you do not, and are using it, you should deactivate and secure it.
- The use of a GPS repeater inappropriately is an enforceable event from both the FAA and the FCC.



GPS repeaters

- FAA is seeing the use of GPS repeaters inappropriately, if you are operating one you should have an FCC license, if you do not, and are using it, you should deactivate and secure it.
- The use of a GPS repeater inappropriately is an enforceable event from both the FAA and the FCC.



Suspected Unapproved Parts

UNAPPROVED PARTS NOTIFICATION

Aircraft Certification Service



FAA
Aviation Safety

No.: 2026-AAE-EHL-20250805-430

Date: 3/18/2026

<http://www.faa.gov/aircraft/safety/programs/sups/upn>

AFFECTED PRODUCTS

Fiberlites and all sub-assembly articles manufactured and sold by Superior Panel Technology for installation on Federal Aviation Administration (FAA) type-certificated (TC) products.

The table below lists the applicable article numbers:

Nomenclature	Article Number
Fiberlite Aircraft Lighting System	FL318
Fiberlite Aircraft Lighting System (DG, VSI, ALT) with cut-out in one corner	FL318CO



Suspected Unapproved Parts

- PURPOSE
- This notification advises all aircraft owners, operators, manufacturers, maintenance organizations, parts suppliers, and distributors of the referenced articles manufactured or sold by Superior Panel Technology that the referenced articles may not meet FAA production approval.



§ 21.9 Replacement and modification articles.

- (a) If a person knows, or should know, that a replacement or modification article is reasonably likely to be installed on a type-certificated product, the person may not produce that article unless it is—
 - (1) Produced under a type certificate;
 - (2) Produced under an FAA production approval;
 - (3) A standard part (such as a nut or bolt) manufactured in compliance with a government or established industry specification;
 - (4) A commercial part as defined in § 21.1 of this part;
 - (5) Produced by an owner or operator for maintaining or altering that owner or operator's product;
 - (6) Fabricated by an appropriately rated certificate holder with a quality system, and consumed in the repair or alteration of a product or article in accordance with part 43 of this chapter; or
 - (7) Produced in any other manner approved by the FAA.



Suspected Unapproved Parts

- RECOMMENDATIONS
- FAA regulations require that type-certificated products conform to their type design.



Suspected Unapproved Parts

- RECOMMENDATIONS
- The FAA encourages aircraft owners, operators, manufacturers, maintenance organizations, and parts suppliers and distributors to inspect their aircraft and aircraft parts inventory for the referenced part numbers.



Suspected Unapproved Parts

- RECOMMENDATIONS
- If these Fiberlites are found in existing inventory, the FAA recommends that they be quarantined to prevent installation until a determination can be made regarding their eligibility for installation.



§ 21.8 Approval of articles.

- If an article is required to be approved under this chapter, it may be approved—
 - a) Under a PMA;
 - b) Under a TSO;
 - c) In conjunction with type certification procedures for a product; or
 - d) In any other manner approved by the FAA.



§ 43.13 Performance rules (general).

- (b) Each person maintaining or altering, or performing preventive maintenance, shall do that work in such a manner and use materials of such a quality, that the condition of the aircraft, airframe, aircraft engine, propeller, or appliance worked on will be at least equal to its original or properly altered condition (with regard to aerodynamic function, structural strength, resistance to vibration and deterioration, and other qualities affecting airworthiness).



AC No: 20-62E: Eligibility, Quality, and Identification of Aeronautical Replacement Parts

- b. Acceptable Parts. The following parts may be found to be acceptable for installation on a TC'd product:

(3) Parts for which inspections and tests have been accomplished by appropriately certificated persons authorized to determine conformity to FAA-approved design.



Thank you

Questions?

