

STAR PROPERTY MANAGEMENT

Southwest Texas Residential Portfolio

Final Walk Clearance Report - Las Palmas Unit 8D

1847 Desert Willow Drive, Suite 100 | San Angelo, TX 76901 (325) 555-0192 | starpropertymgmt.com

FINAL WALK CLEARANCE REPORT

Report No.:

SPM-2026-MR-8D-FW

Date Conducted: July 14, 2026

Conducted By: Jaime Salinas, Maintenance Quality Control Lead

Subject:

Las Palmas Apartments - Unit 8D Make-Ready Turnover, Final Walk and Punch-List Clearance

Project Status: PASS - Unit Cleared for Leasing

1. SUMMARY

I conducted this final walk of Unit 8D at Las Palmas Apartments today after John Smith resolved the two punch-list items that had been flagged during the earlier QC inspection. Both corrections were physically verified and found to be complete and workmanlike. Every area of the unit - surfaces, fixtures, flooring, appliances, and HVAC - now meets Star Property Management's make-ready standard. I have updated the unit's condition report status to Pass, and Unit 8D is ready to be listed and shown to prospective tenants.

2. DETAILED FINDINGS

2.1 ENTRY AND HALLWAY

Condition Observed: The entry door operates correctly - hinges are tight, the deadbolt engages without resistance, and the door sweep sits flush against the threshold. The hallway baseboard was one of the two items carried over from the QC inspection: a short section near the linen closet had a visible seam gap and uneven paint sheen. On today's walk I found that John Smith caulked the seam, allowed it to cure completely, and applied a flat-white finish coat that matches the surrounding baseboard. The repair is smooth to the touch and visually consistent with the rest of the trim.

Issues / Follow-Up: No issues observed. This punch-list item is resolved and cleared.

2.2 LIVING ROOM

Condition Observed: The drywall patching done during the in-house repair phase has cured and been sanded level with the surrounding wall. Texture and paint coverage are uniform, and the repair is not apparent under normal room lighting. Baseboards along the perimeter are intact, painted, and adhered. The window blind functions correctly and the window latch engages without binding. No scuffs, holes, or surface defects are present on any wall.

Issues / Follow-Up: No issues observed.

2.3 KITCHEN

Condition Observed: The kitchen faucet replaced during the in-house repair phase is performing correctly. Water flows at normal pressure from both hot and cold positions, the handles move through their full range without stiffness, and no drip is present when the faucet is in the off position. The deep clean completed by

Isela Juarez is holding well: cabinet interiors and faces are free of grease, the range hood filter is seated and clean, the sink basin is free of staining, and the countertop caulk line at the backsplash is continuous with

no gaps.

Issues / Follow-Up: No issues observed. The faucet drip documented at move-out has been fully corrected.

2.4 BEDROOMS

Condition Observed: Touch-up paint applied to the bedroom walls during the turnover is in good condition. The second punch-list item from the QC inspection was a small area adjacent to the closet doorframe in the primary bedroom where the touch-up had dried to a noticeably different sheen from the surrounding wall. John Smith returned and applied an additional feathered coat that brings the sheen into acceptable alignment with the field paint. Coverage is even and the repair blends without a visible boundary. Closet rods and shelving in both bedrooms are secure when tested by hand, and outlet covers are present and flush.

Issues / Follow-Up: No issues observed. Both punch-list items have been verified and cleared on this walk.

2.5 BATHROOM

Condition Observed: The deep clean performed by Isela Juarez remains in excellent condition. The toilet flushes fully and the tank refills to the correct level without running on. The tub and shower enclosure are free of soap scum and staining, grout lines are clean, and the caulk at the tub surround is continuous with no peeling or gaps. The exhaust fan engages when switched and the vent cover is properly seated. The mirror is clean and fully secured to the wall.

Issues / Follow-Up: No issues observed.

2.6 FLOORING - CARPET

Condition Observed: Victor Rios completed carpet cleaning earlier in the turnover cycle to address the staining that Carlos Mendez documented during the move-out walk. On today's final walk I examined the carpet across the living room and both bedrooms. All treated areas have dried completely, pile appearance is uniform, and no residual odor is detectable. The stain locations visible in the move-out documentation are no longer apparent. No new staining or physical damage occurred between the vendor visit and today.

Issues / Follow-Up: No issues observed. Carpet is in rentable condition.

2.7 HVAC - AIR CONDITIONING SYSTEM

Condition Observed: I set the thermostat to Cool, lowered the setpoint below the current ambient temperature, and confirmed the system cycled on within a normal delay. Airflow from both the bedroom and living room supply registers is cool and at adequate volume. A fresh filter is installed in the return air housing, consistent with make-ready protocol. The air handler runs quietly with no unusual vibration or noise, and the area around the unit shows no moisture staining that would suggest a condensate drainage issue. The condensate access cap is seated securely.

Issues / Follow-Up: No performance issues observed. The filter installation date should be entered in the unit maintenance log so the next replacement can be scheduled on the standard 90-day interval at the start of the new tenancy.

2.8 PATIO AND EXTERIOR DOOR

Condition Observed: The patio sliding door moves on its track without dragging and the latch secures firmly in the locked position. The door screen is intact with no tears. The patio surface has been cleared of any belongings or debris left by the previous occupant. The exterior light fixture at the patio is functional. The door frame and weatherstripping show no damage.

Issues / Follow-Up: No issues observed.

3. RECOMMENDATIONS AND NEXT STEPS

1. **ACTIVATE LISTING** - Unit 8D is cleared for leasing as of today. Brooke Phillips and the leasing team should update the unit's availability status in HubSpot and activate any pending listing placements promptly,

as the make-ready cycle is complete. 2. HVAC FILTER LOG - The replacement filter installed during this turnover should have its installation date recorded in the unit maintenance log so the 90-day replacement interval is tracked correctly from the beginning of the new tenancy. 3. PUNCH-LIST CLOSURE IN AIRTABLE - The two items flagged during the QC inspection have both been physically resolved and verified. The make-ready task record for Unit 8D in Airtable should be confirmed as reflecting the current Pass status, with all subtask fields for the baseboard repair and bedroom paint touch-up marked complete. 4. CONDITION REPORT FILING - The updated condition report carrying the Pass status should be saved to the shared document drive under the Las Palmas Unit 8D folder and linked from the unit's Airtable record so leasing staff can reference it when the incoming resident completes their move-in walk. 5. OWNER NOTIFICATION - Carlos Mendez or Brooke Phillips should advise the property owner that Unit 8D has completed the full make-ready cycle and is rent-ready, providing a brief summary of the scope of work completed, consistent with standard owner relations reporting practices.

Report Prepared By: Jaime Salinas Maintenance Quality Control Lead Star Property Management July 14, 2026

Unit 8D Condition Report Status: PASS