

STAR PROPERTY MANAGEMENT

Southwest Texas Residential Portfolio

Final Walk Clearance Report - Las Palmas Unit 8D

1200 West Commerce Drive, Suite 110 | San Antonio, TX 78207 (210) 555-0194 | starpropertymgmt.com

FINAL WALK CLEARANCE REPORT - LAS PALMAS UNIT 8D

Report No.: SPM-2026-LPK8D-FWC

Date of Assessment: July 14, 2026

Conducted By:

Jaime Salinas, QC Inspector / Property Assessment Lead

Subject Property:

Las Palmas Apartments - Unit 8D

Turn Coordinator:

Carlos Mendez

Maintenance Lead:

John Smith

Assisting Personnel: James Bennett, Victor Rios, Isela Juarez

Authorizing Manager: Brooke Phillips

Report Status:

FINAL - Unit Cleared

-

I. EXECUTIVE SUMMARY

-

Following the identification of two open punch-list items during the prior QC walk-through of Las Palmas Unit 8D, I returned to the unit today to verify that all outstanding deficiencies had been corrected before the unit is returned to available inventory. John Smith completed both repairs within one business day of receiving the punch-list, and upon my reinspection this morning I confirmed that all previously noted concerns have been resolved to a rent-ready standard. Every area of the unit - including repainted surfaces, re-caulked trim, replaced fixtures, cleaned carpet, and deep-cleaned bathrooms and kitchen - was examined and found to be in acceptable condition. The condition report for Unit 8D has been updated to reflect a status of Pass, and the unit is cleared for leasing.

-

II. DETAILED FINDINGS

-

2.1 ENTRYWAY AND FRONT DOOR

Condition Observed: I examined the entry door, threshold, kick plate, and adjacent wall surface. The door seals evenly against the frame with no daylight gaps, the deadbolt engages and releases cleanly, and touch-up paint along the lower entryway wall applied during the in-house repair phase has fully cured and blends consistently with the surrounding surface.

Issues / Follow-Up: No issues observed. This area was not part of the punch-list and remained in satisfactory

condition from the earlier inspection phase.

2.2 HALLWAY BASEBOARD - PUNCH-LIST ITEM 1 (REINSPECTION)

Condition Observed: The hallway baseboard along the north wall was flagged during the prior QC walk for uneven paint coverage and a gap at the wall joint that required re-caulking. I inspected the same stretch today and found that the joint has been re-caulked with a smooth, fully set bead and a fresh paint coat has been applied across the affected section. Coverage is even, no drips or thin spots are visible, and the finish is consistent with the remainder of the baseboard run.

Issues / Follow-Up: Punch-list item fully resolved. No further action is needed in this area. 2.3 PRIMARY BEDROOM WALL PATCH - PUNCH-LIST ITEM 2 (REINSPECTION)

Condition Observed: The second punch-list item concerned the drywall repair area in the primary bedroom, where the initial finish coat did not match the sheen of the surrounding wall. I examined the patch under both natural window light and overhead lighting. John Smith applied an additional blending coat, and the repaired area is no longer distinguishable from the adjacent wall surface. Texture consistency and sheen level are both acceptable.

Issues / Follow-Up: Punch-list item fully resolved. The wall is in rent-ready condition.

2.4 KITCHEN - FAUCET, FIXTURES, AND SURFACES

Condition Observed: The kitchen faucet, which was replaced during the in-house repair phase to eliminate a persistent drip, was tested at full pressure for approximately sixty seconds. No leakage was observed at the spout or at the supply line connections beneath the sink. Cabinet interiors are clean and free of debris. Countertops, the range top, and the oven interior all remain in the clean condition established during Isela Juarez's deep-clean and show no new soiling.

Issues / Follow-Up: No issues observed. The kitchen is in full rent-ready condition.

2.5 BATHROOMS - FIXTURES AND CLEANLINESS

Condition Observed: I inspected both the main bathroom and the secondary half-bath. Toilets flush properly and do not run after the tank refills. Faucet handles turn without stiffness and shut off completely. Grout lines in the shower surround are clean and uniform, and the tile surfaces show no residual staining from prior

occupancy. The deep-clean completed by Isela Juarez addressed all bathroom surfaces, and that condition is holding.

Issues / Follow-Up: No issues observed. Both bathrooms are rent-ready.

2.6 LIVING AREA AND BEDROOM CARPET

Condition Observed: Carpet throughout the living area and bedroom was professionally cleaned by Victor Rios prior to this final walk. The fibers are dry, even in appearance, and free of any detectible odor. The staining documented by Carlos Mendez during the original move-out walk has been fully remediated. Hard flooring surfaces in the kitchen and bathrooms are clean and free of streaks or adhesive residue.

Issues / Follow-Up: No issues observed. All flooring is in acceptable rent-ready condition.

2.7 HVAC - VENTS AND THERMOSTAT

Condition Observed: I checked all supply and return vent covers for cleanliness and secure attachment. Each cover was wiped down during the deep-clean phase and shows no dust accumulation. The thermostat is operational and set to the standard vacant-unit temperature. No unusual sounds from the air handler were detected during the time I spent in the unit.

Issues / Follow-Up: No deficiency observed during this walk. A full HVAC coil cleaning falls outside the scope of this make-ready turn and should be added to the property's next scheduled preventive maintenance cycle.

2.8 WINDOWS, BLINDS, AND INTERIOR GLASS

Condition Observed: All window latches lock and release properly. No cracked panes were found. Blinds in the living room and bedroom are intact with no broken slats. Interior glass surfaces were wiped down during the deep-clean and show no streaking under direct light.

Issues / Follow-Up: No issues observed.

2.9 GENERAL UNIT PRESENTATION

Condition Observed: Walking the unit as a whole, it presents cleanly with no debris, no items left by the prior tenant, and no lingering odors. All light switches and outlet covers are in place. Interior door hardware bedroom door, closet doors, and bathroom door - operates without sticking or misalignment. The unit is in a condition suitable for immediate leasing showings.

Issues / Follow-Up: No issues observed. The unit is ready to be activated in the leasing pipeline.

-

III. RECOMMENDATIONS AND NEXT STEPS

-

1. ACTIVATE LISTING IN HUBSPOT - The assigned leasing agent should update the Las Palmas Unit 8D record in the HubSpot leasing CRM to reflect an available status so that prospective applicants currently in the pipeline can be scheduled for showings without delay. 2. CONFIRM MAKE-READY RECORD CLOSURE - The make-ready turn record for Unit 8D should be marked complete with a condition status of Pass so the full audit trail is preserved for owner reporting and future reference. 3. NOTIFY BROOKE PHILLIPS - Brooke Phillips should be informed that Unit 8D has cleared the final walk and is back in available inventory, enabling her to include an updated availability note in the next owner-relations communication. 4. LOG HVAC COIL CLEANING FOR NEXT PM CYCLE - James Bennett or the lead maintenance coordinator should add Las Palmas Unit 8D to the work-order queue for coil cleaning at the next scheduled preventive maintenance round, as this item was not within scope of the current turn. 5. ARCHIVE PHOTO DOCUMENTATION - The close-up photographs of the baseboard and hallway captured during the QC inspection phase should be saved to the shared document drive under the Las Palmas Unit 8D make-ready folder as a permanent record of pre- and post-remediation conditions. 6. CLOSE OUT VENDOR RECORDS - Carlos Mendez should confirm that Victor Rios's carpet cleaning documentation has been filed and that no open vendor items remain associated with this turn.

-

IV. FINAL DISPOSITION

-

Unit Status:

PASS - Cleared for Leasing

Date Cleared: July 14, 2026 All punch-list items identified during the prior QC inspection have been satisfactorily resolved. This unit is released from the make-ready workflow and is approved for occupancy.

-

Prepared and submitted by:

Jaime Salinas QC Inspector / Property Assessment Lead Star Property Management July 14, 2026
