51单片机库源码

输入设备

1. 独立按键

```
* @brief 获取独立按键键码
 * @param 无
 * @retval 按下按键的键码,范围: 0~4,无按键按下时返回值为0
 */
unsigned char Key()
   unsigned char KeyNumber=0;
   if(P3_1==0) {Delay(20); while(P3_1==0); Delay(20); KeyNumber=1;}
   if(P3_0==0) {Delay(20); while(P3_0==0); Delay(20); KeyNumber=2;}
   if(P3_2==0) {Delay(20); while(P3_2==0); Delay(20); KeyNumber=3;}
   if(P3_3==0) {Delay(20); while(P3_3==0); Delay(20); KeyNumber=4;}
   return KeyNumber;
}
#ifndef __KEY_H__
#define ___KEY_H__
unsigned char Key();
#endif
```