9. General Diagnostic Table

A: INSPECTION

1. IMPROPER VEHICLE POSTURE OR IMPROPER WHEEL ARCH HEIGHT

Possible cause	Corrective action	
(1) Deformation or damage of suspension parts	Replace.	
(2) Defective strut COMPL or shock absorber COMPL	Replace.	
(3) Improper installation of strut assembly or shock absorber assembly	Replace with appropriate parts.	
(4) Installation of the wrong coil spring	Replace with appropriate parts.	

2. POOR RIDE COMFORT

- 1) Large rebound shock
- 2) Rocking of the vehicle continues too long after running over bump and hump.
- 3) Excessive shock in bumping

Possible cause	Corrective action	
(1) Damaged coil spring	Replace.	
(2) Overinflation of tires	Adjust.	
(3) Improper wheel arch height	Replace the coil springs with new parts.	
(4) Fault in operation of strut or shock absorber	Replace.	
(5) Damage or deformation of strut mount or shock absorber mount	Replace.	
(6) Unsuitable length (maximum or minimum) of strut or shock absorber	Replace with appropriate parts.	
(7) Abnormal deformation or loss of bushing	Replace.	
(8) Deformation or damage of helper in strut assembly or shock absorber	Replace.	
(9) Oil leakage from the strut or shock absorber	Replace.	

3. NOISE

Possible cause	Corrective action	
(1) Wear or damage of strut or shock absorber component parts	Replace.	
(2) Loosening of the suspension link installing bolt	Tighten to the specified torque.	
(3) Abnormal deformation or loss of bushing	Replace.	
(4) Unsuitable length (maximum or minimum) of strut or shock absorber	Replace with appropriate parts.	
(5) Damaged coil spring	Replace.	
(6) Wear or damage of the ball joint	Replace.	
(7) Deformation of the clamp - stabilizer bushing	Replace.	

REAR SUSPENSION

RS

		Page
1.	General Description	2
	Wheel Alignment	
	Rear Sub Frame	
4.	Rear Stabilizer	14
5.	Rear Trailing Link	16
6.	Upper Arm	19
7.	Front Lateral Link	21
8.	Rear Lateral Link	24
9.	Rear Shock Absorber	27
0	General Diagnostic Table	31