Controller

Look | **Filter** | Layers&Gos | Netlist | Selection | Inspector | Settings

Hierarchy Settings

Hierarchy Start Level   `0`

Hierarchy Stop Level   `99`

- [x] Process Master Cells
- [ ] Process Terminal Cells
- [x] Process Components

Rubbers
- ( ) Centric   (•) Barycentric   ( ) Steiner

Layout Mode
- (•) Symbolic (lambda)   ( ) Real (foundry grid)   ( ) nanometer   ( ) micrometer