

OpenCore

Errata Sheet

[2020.06.22]

1 Introduction

This document provides information on select issues discovered in the relessed versions of OpenCore and provides workarounds whenever possible. This document is updated after OpenCore is released and is thus not contained in the binary packages.

This document contains issues considered causing significant impact on the end-user. More details on all known issues including feature requests and development version issues can be found at Acidanthera Bugtracker.

2 Issue list

• Identifier: ERR059-1

Published: 2020-06-02 08:06 MSK Updated: 2020-06-21 18:22 MSK

Affected versions: 0.5.9 Resolved in: 0.6.0 (9d5aa267)

Description:

Boot picker menu may not show when upgrading macOS with the following error:

 ${\tt OCUI: Entry \; kind \; 16 \; unsupported \; for \; Icon OCB: \; Show Menu \; failed \; \hbox{--} \; Unsupported} \\$

Halting on critical error

Possible workarounds:

- Add run-efi-updater variable with NO string value OR
- Avoid using OpenCanopy OR
- Disable showing picker by setting ShowPicker to false OR
- Update to master version

• Identifier: ERR059-2

Published: 2020-06-02 08:06 MSK **Updated**: 2020-06-21 18:22 MSK

Affected versions: 0.5.9 Resolved in: 0.6.0 (670d4e0c)

Description:

Incorrect operating system may be selected as the default during macOS upgrade when Windows and macOS are installed on the same disk. Reference: acidanthera/bugtracker#948.

Possible workarounds:

- Add run-efi-updater variable with NO string value OR
- Install Windows on a separate disk OR
- Update to master version

• Identifier: ERR059-3

Published: 2020-06-21 18:22 MSK **Updated**: 2020-06-21 18:22 MSK

Affected versions: 0.5.9 Resolved in: 0.6.0 (2449e47c)

Description:

DEBUG builds may fail to load due to unaligned access assertion when accessing device paths. Reference: acidanthera/bugtracker#951.

Possible workarounds:

- Avoid using DEBUG builds OR
- Update to master version