

DELL9380 – FAULT SHEET

METADATA

- **PUBLISHED:** 05/01/2025
- **FILE ID:** DELL9380-20260105-FAULT_SHEET

BRIEF

- Fingerprint sensor – recessed in but functional
- Screen – Large 100mm scratch top left screen, does not impact function of screen
- Frame – General wear

DETAILS

1. The **FINGER PRINT SENSOR** has been bent inwards to the frame causing it to look recessed in. This however does not impact functionality¹².
2. The main **DISPLAY/SCREEN** has a large 100mm (*approximate*) scratch deep enough to be visible with direct white light. Damage does not cause any issues with display output.
3. The **FRAME** and **CHASIS** has general use wear. Dents³ seen on side of case

¹ EXHIBIT: DELL9380-20251224-IMG_8467

² EXHIBIT: DELL9380-20251224-IMG_8470

³ EXHIBIT: DELL9380-20251224-IMG_8468