


AVR - HW7

임베디드스쿨1기 Lv1과정 2020. 10. 30 박하늘

1. [Review] T/C CTC Mode

- Clear Timer on Compare Match
 - BOTTOM 에서 설정된 OCR(MAX가 아님) 값과 같아지면 0으로 클리어되며 인터럽트 발생



 $f_{OCn} = \frac{f_{\text{clk_I/O}}}{2 \cdot N \cdot (1 + OCRn)}$ N : Prescaler 분주비 2: Toggle

→ TCNT의 counting개수를 조절하면 주기가 바뀜. 즉, 주기를 이용해서 duty 제어



1. [Review] T/C CTC Mode waveform Generation

```
#define F_CPU 16000000UL
 #include <avr/io.h>
 #include <avr/interrupt.h>
 #define sbi(PORTX, BitX) (PORTX |= (1 << BitX))</pre>
 #define cbi(PORTX, BitX) (PORTX &= ~(1 << BitX))
 volatile unsigned int counter = 0;
 void CTC_timer_Init(void);
GSIGNAL(TIMERO_COMPA_vect)
int main(void)
     CTC_timer_Init();
     while(1)
gvoid CTC_timer_Init(void)
     cbi(SREG, 7);
     sbi(TCCR0A, WGM01);
     sbi(TCCR0A, COM0A0);
     TCCR0B = (1 << CS02) | (1 << CS00);
     TIMSK0 = (1 << OCIE0A);
     OCRØA = 255;
     DDRD = 0xff;
     PORTD =0xff;
     sbi(SREG,7);
```

1. sbi(TCCR0A, WGM01); //TOP: OCRA

TCCR0A - Timer/Counter Control Register A

Bit	7	6	5	4	3	2	1	0	
0x24 (0x44)	COM0A1	COM0A0	COM0B1	COM0B0	ı	-	WGM01	WGM00	TCCR0A
Read/Write	R/W	R/W	R/W	R/W	R	R	R/W	R/W	'
Initial Value	0	0	0	0	0	0	0	0	

Mode	WGM02	WGM01	WGM00	Timer/Counter Mode of Operation	ТОР	Update of OCRx at	TOV Flag Set on ⁽¹⁾⁽²⁾
0	0	0	0	Normal	0xFF	Immediate	MAX
1	0	0	1	PWM. phase correct	0xFF	TOP	BOTTOM
2	0	1	0	CTC	OCRA	Immediate	MAX
3	0	1	1	Fast PWM	0xFF	воттом	MAX
4	1	0	0	Reserved	-	_	_
5	1	0	1	PWM, phase correct	OCRA	TOP	воттом
6	1	1	0	Reserved	-	_	_
7	1	1	1	Fast PWM	OCRA	воттом	TOP

2. sbi(TCCR0A, COM0A0); //OCRA와 비교하여 토글

Table 14-2. Compare Output Mode, non-PWM Mode

COM0A1	COM0A0	Description
0	0	Normal port operation, OC0A disconnected.
0	1	Toggle OC0A on compare match
1	0	Clear OC0A on compare match
1	1	Set OC0A on compare match

3. TCCR0B = (1 << CS02)|(1 << CS00) // 1024로 분주

16MHz/1024 = 15624 hz

1/15624 = 0.000064 sec

0.000064 * 256 = 0.0164 sec

Duty: 16.4 msec, 주기: 32.8msec

1	0	0	clk _{wo} /256 (from prescaler)
1	0	1	clk _{I/O} /1024 (from prescaler)
1	1	0	External clock source on T0 pin. Clock on falling edge.
1	1	1	External clock source on T0 pin. Clock on rising edge.



1. [Review] T/C CTC Mode waveform Generation

```
#define F_CPU 16000000UL
 #include <avr/io.h>
 #include <avr/interrupt.h>
 #define sbi(PORTX, BitX) (PORTX |= (1 << BitX))
 #define cbi(PORTX, BitX) (PORTX &= ~(1 << BitX))
 volatile unsigned int counter = 0;
 void CTC_timer_Init(void);
GSIGNAL(TIMERO_COMPA_vect)
int main(void)
    CTC_timer_Init();
    while(1)
gvoid CTC_timer_Init(void)
     cbi(SREG, 7);
    sbi(TCCR0A, WGM01);
    sbi(TCCR0A, COM0A0);
    TCCR0B = (1 << CS02) | (1 << CS00);
    TIMSK0 = (1 << OCIE0A);
    OCRØA = 255;
    DDRD = 0xff;
    PORTD =0xff:
     sbi(SREG,7);
```

4. TIMSK0 = (1<<OCIE0A); //CIE0A: Timer/Counter0
Output Compare Match A Interrupt Enable

5. OCR0A = 255; // 255로 Top값을 정한다.
DDRD = 0xff; //모두 출력으로 사용하겠다(LED사용)
PORTD = 0xff; //5V 출력 사용


6. SIGNAL(TIMER0_COMPA_vect) //main문에 함수를 집어넣지 않아도 HW차원에서 함수를 호출한다. 즉, 타이머 오버플로우 되었을때 인터럽트 실행



1. [Review] T/C Fast PWM Mode

■ Fast PWM Mode

- BOTTOM → MAX로 단순 증가하다 OCR값과 비교해 같아지면 OC=0으로 클리어
- COM 비트 설정에 따라 반전 비반전 출력 토글 가능



→ 주기가 일정하면서 duty를 제어할때 사용



1. [Review] T/C Fast PWM Mode

```
#define F_CPU 16000000UL
 #include <avr/io.h>
 #include <avr/interrupt.h>
 #define sbi(PORTX, BitX) (PORTX = (1 << BitX))
 #define cbi(PORTX, BitX) (PORTX &= ~(1 << BitX))
 volatile unsigned int counter = 0;
 void Fast PWM Mode(void);
∃SIGNAL(TIMER0_COMPA_vect)
     OCR0A += 1;
    if(OCR0A == 255)
         OCRØA = 0:
∃int main(void)
     Fast_PWM_Mode();
     while(1)
∃void Fast PWM Mode(void)
     cbi(SREG, 7);
     sbi(TCCR0A, WGM00);
    sbi(TCCR0A, WGM01);
     sbi(TCCR0A, COM0A1);
    TCCR0B = (1 << CS02) (1 <<CS00);
    TIMSK0 = (1 << OCIE0A);
     OCR0A = 0;
     DDRD = 0xff;
     PORTD =0x00;
     sbi(SREG,7);
```

1. sbi(TTCR0A, WGM00) sbi(TTCR0A, WGM01); // Fast PWM Mode

Mode	WGM02	WGM01	WGM00	Timer/Counter Mode of Operation	ТОР	Update of OCRx at	TOV Flag Set on ⁽¹⁾⁽²⁾
0	0	0	0	Normal	0xFF	Immediate	MAX
1	0	0	1	PWM, phase correct	0xFF	TOP	воттом
2	0	1	0	CTC	OCRA	Immediate	MAX
3	0	1	1	Fast PWM	0xFF	воттом	MAX
4	1	0	0	Reserved	-	-	-
5	1	0	1	PWM, phase correct	OCRA	TOP	воттом
6	1	1	0	Reserved	-	_	_
7	1	1	1	Fast PWM	OCRA	воттом	TOP

2. sbi(TCCR0A, COM0A1); //OC0A의 BOTTOM일때 1, OC0A와 매치되면 0

	COM0A1	COM0A0	Description
	0	0	Normal port operation, OC0A disconnected.
	0	1	WGM02 = 0: Normal port operation, OC0A disconnected. WGM02 = 1: Toggle OC0A on compare match.
	1	0	Clear OC0A on compare match, set OC0A at BOTTOM, (non-inverting mode).
3.	1	1	Set OC0A on compare match, clear OC0A at BOTTOM, (inverting mode).


- 4. DDRD = 0xff; //DDRD들 5V술덕으로 쓸 것이나. PORTD = 0x00; //없어도 됨
- 5. HW 인터럽트 발생시, OCRA ++(counter)하여, 255 넘으면 OCRA 0 (timer)으로 됨



1. [Review] T/C Phase Correct PWM Mode

■ PC PWM Mode

: Dual Slope Operation이라서 Fast PWM 보다 동작 주파수가 작다. 하지만, 대칭적인 특징이 있어서 모터 제어 응용에 많이 사용된다.



→ 원신호의 주기는 일정하지만, 출력되는 주기는 제어됨 (Phase 제어)



1. [Review] T/C Phase Correct PWM Mode

```
#define F_CPU 16000000UL
#include <avr/io.h>
#include <avr/interrupt.h>
#define sbi(PORTX, BitX) (PORTX |= (1 << BitX))
#define cbi(PORTX, BitX) (PORTX &= ~(1 << BitX))
volatile unsigned int counter = 0;
void Phase_Correct_PWM_Init(void);
SIGNAL(TIMERO_COMPA_vect)
    OCR0A += 1;
    if(OCR0A == 255)
        OCROA = 0;
int main(void)
    Phase_Correct_PWM_Init();
    while(1)
void Phase_Correct_PWM_Init(void)
    cbi(SREG, 7);
    sbi(TCCR0A, WGM02);
    sbi(TCCR0A, WGM00);
    sbi(TCCR0A, COM0A1);
    TCCR0B = (1 << CS02) (1 <<CS00);
    TIMSK0 = (1 << OCIE0A);
    OCR0A = 0;
    DDRD = 0xff;
    //PORTD =0x00:
    sbi(SREG,7);
```

1. sbi(TTCR0A, WGM02) sbi(TTCR0A, WGM00); // Phase Correct PWM Mode

Mode	WGM02	WGM01	WGM00	Timer/Counter Mode of Operation	ТОР	Update of OCRx at	TOV Flag Set on ⁽¹⁾⁽²⁾
0	0	0	0	Normal	0xFF	Immediate	MAX
1	0	0	1	PWM, phase correct	0xFF	TOP	BOTTOM
2	0	1	0	CTC	OCRA	Immediate	MAX
3	0	1	1	Fast PWM	0xFF	воттом	MAX
4	1	0	0	Reserved	-	_	-
5	1	0	1	PWM, phase correct	OCRA	TOP	воттом
6	1	1	0	Reserved	-	_	-
7	1	1	1	Fast PWM	OCRA	BOTTOM	TOP

2. sbi(TCCR0A, COM0A1); //OC0A와 비교할때 upcounting시 0, downcounting시 1

COM0A1	COM0A0	Description
0	0	Normal port operation, OC0A disconnected.
0	1	WGM02 = 0: Normal port operation, OC0A disconnected. WGM02 = 1: Toggle OC0A on compare match.
1	0	Clear OC0A on compare match when up-counting. Set OC0A on compare match when down-counting.
1	1	Set OC0A on compare match when up-counting. Clear OC0A on compare match when down-counting.


- 4. DDRD = 0xff; //DDRD들 5V술덕으로 쓸 것이나.
- 5. HW 인터럽트 발생시, OCRA ++(counter)하여, 255 넘으면 OCRA 0 (timer)으로 됨



1. [Review] T/C CTC Mode waveform Generation

```
#define F_CPU 16000000UL
#include <avr/io.h>
#include <avr/delay.h>
#include <avr/interrupt.h>
#define sbi(PORTX, BitX) (PORTX |= (1 << BitX))</pre>
#define cbi(PORTX, BitX) (PORTX &= ~(1 << BitX))
volatile unsigned int counter = 0;
void SG_Fast_PWM_MODE(void);
int main(void)
    SG_Fast_PWM_MODE();
    while(1)
        OCR1A = 2000;
        deLay ms(1000);
        OCR1A = 3000;
        _deLay_ms(1000);
        OCR1A = 4000;
        _delay_ms(1000);
        OCR1A = 3000;
        _deLay_ms(1000);
void SG_Fast_PWM_MODE(void)
    cbi(SREG, 7);
    sbi(TCCR1A, COM1A1);
    sbi(TCCR1A, COM1B1);
    sbi(TCCR1A, WGM11);
    sbi(TCCR1B, WGM13);
    sbi(TCCR1B, WGM12);
    sbi(TCCR1B, CS11);
    ICR1 = 39999;
    DDRB = (1 << PORTB1);
    sbi(SREG,7);
```

1. Servo Motor Datasheet



	Mode	WGM13	WGM12 (CTC1)	WGM11 (PWM11)	WGM10 (PWM10)	Timer/Counter Mode of Operation	ТОР	Update of OCR1x at	TOV1 Flag Set on
	0	0	0	0	0	Normal	0xFFFF	Immediate	MAX
	1	0	0	0	1	PWM, phase correct, 8-bit	0x00FF	TOP	воттом
	2	0	0	1	0	PWM, phase correct, 9-bit	0x01FF	TOP	воттом
	3	0	0	1	1	PWM, phase correct, 10-bit	0x03FF	TOP	ВОТТОМ
	4	0	1	0	0	CTC	OCR1A	Immediate	MAX
	5	0	1	0	1	Fast PWM, 8-bit	0x00FF	BOTTOM	TOP
	6	0	1	1	0	Fast PWM, 9-bit	0x01FF	воттом	TOP
	7	0	1	1	1	Fast PWM, 10-bit	0x03FF	воттом	TOP
	8	1	0	0	0	PWM, phase and frequency correct	ICR1	воттом	воттом
	9	1	0	0	1	PWM, phase and frequency correct	OCR1A	воттом	воттом
	10	1	0	1	0	PWM, phase correct	ICR1	TOP	воттом
	11	1	0	1	1	PWM, phase correct	OCR1A	TOP	ВОТТОМ
	12	1	1	0	0	CTC	ICR1	Immediate	MAX
	13	1	1	0	1	(Reserved)	-	-	-
f	14	1	1	1	0	Fast PWM	ICR1	воттом	TOP =
	15	1	1	1	1	Fast PWM	OCR1A	BOTTOM	TOP



포기하면 얻는 건 아무것도 없다.

1. [Review] 16bit T/C PWM Servo Motor

```
#define F_CPU 16000000UL
#include <avr/io.h>
#include <avr/delay.h>
#include <avr/interrupt.h>
#define sbi(PORTX, BitX) (PORTX |= (1 << BitX))
#define cbi(PORTX, BitX) (PORTX &= ~(1 << BitX))
volatile unsigned int counter = 0;
void SG_Fast_PWM_MODE(void);
int main(void)
    SG_Fast_PWM_MODE();
    while(1)
        OCR1A = 2000;
        _delay_ms(1000);
        OCR1A = 3000;
        _delay_ms(1000);
        OCR1A = 4000;
        _delay_ms(1000);
        OCR1A = 3000;
        _delay_ms(1000);
void SG_Fast_PWM_MODE(void)
    cbi(SREG, 7);
    sbi(TCCR1A, COM1A1);
    sbi(TCCR1A, COM1B1);
    sbi(TCCR1A, WGM11);
    sbi(TCCR1B, WGM13);
    sbi(TCCR1B, WGM12);
    sbi(TCCR1B, CS11);
    ICR1 = 39999;
    DDRB = (1 << PORTB1);
    sbi(SREG,7);
```

3. sbi(TCCR1A, COM1A1); sbi(TCCR1A, COM1B1); // non-inverting mode 사용

Table 15-3. Compare Output Mode, Fast PWM(1)

COM1A1/COM1B1	COM1A0/COM1B0	Description
0	0	Normal port operation, OC1A/OC1B disconnected.
0	1	WGM13:0 = 14 or 15: Toggle OC1A on compare match, OC1B disconnected (normal port operation). For all other WGM1 settings, normal port operation, OC1A/OC1B disconnected.
1 0		Clear OC1A/OC1B on compare match, set OC1A/OC1B at BOTTOM (non-inverting mode)
1	1	Set OC1A/OC1B on compare match, clear OC1A/OC1B at BOTTOM (inverting mode)

4. sbi(TCCR1B, CS11); //16Mhz/8 = 2Mhz

	CS12	CS11	CS10	Description	
_	0	0	0	No clock source (Timer/Counter stopped).	
ξ,	0	0	1	clk _{I/O} /1 (no prescaling)	_
(0	1	0	clk _{I/O} /8 (from prescaler)	

6. ICR1로 TCTNT0의 끝을 조절하고, OCR로 제어하면 duty비 제어 가능



2. [Preview] SPI - Serial Peripheral Interrupt

1) SPI란?


: MOSI, MISO, SCK, /SS의 4개 통신선을 이용하는 (전이중) 고속 동기식 직렬통신 방식이다. 이는 UART 통신 규격에 비하여 빠른 속도와 멀티 통신이 지원되며, I2C (반이중) 통신 규격에 비하여 빠르며 간단한 제어가 가능하, 1:n의 통신도 가능하다는 장점이 있다.


2) SPI 특징?

- Full-duplex, three-wire synchronous data transfer
- Master or slave operation
- LSB first or MSB first data transfer
- Seven programmable bit rates
- End of transmission interrupt flag
- Write collision flag protection
- Wake-up from idle mode
- Double speed (CK/2) master SPI mode

▶ 항상 Master와 Slave사이에서 직렬로 데이터를 송수신, 클럭은 항상 Master가 발생

▶ Wake-Up : 슬립모드 해제 기능






MOSI(Master Out Slave IN): 마스터 → 슬레이브 데이터 전송선 MISO(Master In Slave Out): 슬레이브 → 마스터 데이터 전송선 (SPI 송신이 곧 수신임. → 송수신의 타이밍을 결정짓는 것은 Master장치)

- -SCLK, CLK(Clock): 동기화 신호를 위한 Clock
- -SS, CS(Slave Select, Chip Select): Master가 여러개의 Slave중 어디로 보낼지 결정하는 신호선




2. [Preview] SPI – Serial Peripheral Interrupt

3) SPI Pin Description?



Shift Register에 의해서 데이터가 이동. 마스터가 어떤값을 슬레이브로 보낼때, 1 클럭의 신호마다 1비트의 데이터가 이동함.

• 기본적으로 MSB부터 전송되는데 특정 컨트롤러는 LSB부터 전송을 수행시키는 방법도 지원한다.







감사합니다.