In our Pioneers project, we had a few issues such as our original screen- the Nokia 5110 screen- uses the same SPI GPIO pins as the NFC/RFID reader. Sadly due to time constraints, and after a skype meeting and lots of emails, it was decided that we had to use a standard 16x2 LCD screen. Other issues included the original soldering iron burning one of our NFC/RFID readers, when we were soldering the pins.

Some of the future enhancements include getting the Nokia 5110 screen to work, building multiple NFC devices and turning it into an event.