In our Pioneers project, we had a few issues such as our original screen- the Nokia 5110 screen- uses the same SPI GPIO pins as the NFC/RFID reader. Sadly due to time constraints, and after a skype meeting and lots of emails, it was decided that we had to use a standard 16x2 LCD screen. Other issues included the original soldering iron buring one of our NFC/RFID readers, when we were soldering the pins.