

T.Embling Hospital

Site QA
*Standard ITP - Aus Standards - Wet Area Waterproofing WP-08 TREMCO VULKEM 350R/951NF
BUILDING C&F



Report summary



Name	Status	Last Activity
*Standard ITP - Aus Standards - Wet Area Waterproofing WP-08 TREMCO VULKEM 350R/951NF	F BUILDING C&F - page 3	No Activity na

JH (SK)

- Include sketch of waterproofing detail being used
- photos are to be included of each layer being applied
- Confirm how moisture content is being measured

*Standard ITP - Aus Standards - Wet Area Waterproofing WP-08 TREMCO VULKEM 350R/ 951NF BUILDING C&F



Add required inputs

Level: Zone:

replace this statement. "Moisture content in the concrete must be lower than 4.5% as measured using a Tramex CME Moisture Meter" [Vulkem 350R/951NF datasheet].

2 - Construction Inspections

2.1 - Concrete moisture content check - measure moisture content of concrete substrate - note details on checklist with photo of readout			
Specification Reference - ASTM F2170, A53740 cl 4.4.3 / GBA-SPE-AR-AS-0001			
Acceptance Criteria - Slabs require a relative humidity of less than 75%			
Test/ Inspection - Measurement			
Test/Inspection Frequency - Each wet area What is the number of inspection frequency?			
Inspection: Subcontractor - WS (I) EVERY 20M2			
Inspection: John Holland - PE (S)			
2.2 - Drainage installation - puddle flange installation			
Specification Reference - AS3740 fig 4.3.1 / GBA-SPE-AR-AS-0001			
Acceptance Criteria - Installed rebated in substrate, undamaged, capped to prevent ingress of debris			
Test/ Inspection - Installation and Inspection			
Test/Inspection Frequency - Each wet area			
Inspection: Subcontractor - HS (I)			
Inspection: John Holland - PE (S)			
2.3 - Substrate condition Inspection			
Specification Reference - AS3740 cl 4.4.1, JHG ETN-00006 3.4 / GBA-SPE-AR-AS-0001			
Acceptance Criteria - Clean and free of laitence/debris, holes patched			
Test/ Inspection - Inspection			
Test/Inspection Frequency - Each wet area			
Inspection: Subcontractor - WS (I)			
Inspection: John Holland - PE (S)			

Specification Reference - AS3740 cl 2.3.1 / 2.3.2 Acceptance Criteria - Falls are to the drain - min 1:80 in shower area, otherwise 1:100			
Test/ Inspection - Measurement			
Test/Inspection Frequency - Each wet area			
Inspection: Subcontractor - WS (I)			
Inspection: John Holland - PE (S)			
2.5 - Waterbars installed to edge of shower area and at door openings, waterbars installed to in-wall tap and shower rose surrounds - attach photos of correct installation.			
Specification Reference - AS3740 4.5.3, 4.8, 4.9, 4.12 / GBA-SPE-AR-AS-0001			
Acceptance Criteria - Waterbars in line with approved shop drawings and AS3740 requirements.			
Test/ Inspection - Installation and Inspection			
Test/Inspection Frequency - Each wet area			
Inspection: Subcontractor - WS (I)			
Hold point for Subcontractor: Ensure measurement taken of fall i shower.			
Records & Comments - CREATE HOLD POINT Measured fall:			
2.6 - Bond breaker/fillets for Class 1/2/3 membrane installed to wall/floor junctions - attach photos of correct size			
Specification Reference - AS3740 4.5.3, 4.10 / GBA-SPE-AR-AS-0001			
Acceptance Criteria - Bond Breaker/fillet to XXXX size based on class of membrane			
Test/ Inspection - Measurement			
Test/Inspection Frequency - Each wet area			
Inspection: Subcontractor - WS (I)			
Inspection: John Holland - PE (S)			
2.7 - Subcontractor Pre-placement Check: Confirm temperature is acceptable for membrane installation			
Specification Reference - GBA-SPE-AR-AS-0001			
Acceptance Criteria - Everything ready to install			
Test/ Inspection - Review & Verify			
Test/Inspection Frequency - Each wet area			

	2.7 - Subcontractor Pre-placement Check: Confirm temperature is acceptable for membrane installation				
	Inspection: Subcontractor - WS (I)				
	Inspection: John Holland - PE (S)				
	Records & Comments - Required size: Unclear what is suppose to be measured.				
	PLEASE REMOVE AND REPLACE WITH (TEMPERATURE READING) Measured size:				
	2.8 - HOLD POINT: Inspect substrate and confirm that steps above are complete and that membrane may be applied				
	Specification Reference - GBA-SPE-AR-AS-0001				
	Acceptance Criteria - Previous steps complete in line with the Australian Standards, specifications and ETN				
	Test/ Inspection - Visual Inspection				
	Test/Inspection Frequency - Each wet area				
	Inspection: Subcontractor - WS (W)				
	Inspection: John Holland - PE (I) What is the temperature range that needs to be confirmed in the acceptance				
	Records & Comments - Applicator Names: DO NO APPLY SEALANT TO A SUBSTATE SURFACE IS BELOW 10C OR T SURAFE TEMPERATUREIS ABOUE 40C				
Temperature at placement:					
	2.9 - Apply primer in line with MAMS - take photograph of primer container with technical details and photo/video of application				
	Specification Reference - GBA-SPE-AR-AS-0001				
	What are the acceptable primer than can be used with this product? At lea Acceptance Criteria - Correct primer applied primer used should be recorded to ensure that it is one of the recommende materials listed on the datasheet.				
	Test/ Inspection - Installation and Inspection VULKEM 171 PRIMER				
	Test/Inspection Frequency - Each wet area				
	Inspection: Subcontractor - WS (I) What is MAMS?				
	Inspection: John Holland - PE (W) PLEASE CHANGE MAMS TO DATA SHEET				
	2.10 - Apply membrane layers in line with MAMS and the figures in AS3740 - take photograph of membrane container with technical details and photo/video of application - note details of timing on checklist				
	Specification Reference - GBA-SPE-AR-AS-0001				
	Acceptance Criteria - Each layer applied in line with MAMS requirements, timing between layers in line with the MAMS				
	Test/ Inspection - Installation and Inspection				
	Test/Inspection Frequency - Each wet area				
	Inspection: Subcontractor - WS (I)				

technical details and photo/video of application - note details of timing on checklist			
Inspection: John Holland - PE (W)			
2.11 - HOLD POINT: - Inspection to confirm integrity of the membrane and completion of installation.			
Specification Reference - AS3740 Figures, AS3740 cl 4.5.3, 4.6 / GBA-SPE-AR-AS-0001			
	nuity of the membrane, no installation defects such as pinholes, measure dry film thickness, confirm s and details in the standard		
est/ Inspection - Installatio	What is the minimum curing/drying times for 3 951NF layer for Acceptance criteria?		
est/Inspection Frequency	- Each wet area 5C-12C 24-72 HOURS		
nspection: Subcontractor -	100-290 4-0110010		
nspection: John Holland - P	PE (H)		
Records & Comments - Layer 1 time:	(1) Include notes "Pass or Fail". (2) Where in 2.11 is the film thickness and vertical		
_ayer 2 time:	termination heights recorded for Acceptance Criteria?		
2.12 - Membrane test - Flo	ood / Electronic Leak Detection / Seam Probe test the area in line with the AMS instruction		
Specification Reference - As	53740 cl 4.5.4 / GBA-SPE-AR-AS-0001		
	test - no leakage observed / measured over 24 hours Electronic Leak Detection Test - no points of fied Seam probe test - no seam failures reported		
Fest/ Inspection - Test			
Test/Inspection Frequency	- Each wet area		
nspection: Subcontractor -	WS (I) Who is the "Nominated Authority"?		
nspection: John Holland - P	PE (W) (SITE MANAGER		
nspection: Nominated Autl	hority - DC (W)		
Records & Comments - Observed setting time:	Include "Pass" or "Fail" in notes.		
2.13 - 100% Witness Point	: Supervise the follow-on Subcontractor(s) to ensure protection has been applied to membran		
Specification Reference - Gl	BA-SPE-AR-AS-0001		
Acceptance Criteria - Each l	ayer applied in line with MAMS requirements - dressed into puddle flange		
	on and Inspection		
Fest/ Inspection - Installation			

2.13 - 100% Witness Point: Supervise the follow-on Subcontractor(s) to ensure protection has been applied to membrane.

Inspection: John Holland - PE (I)

3 - Close-Out

3.1 - ITP close-out.		
Specification Reference - GBA-SPE-AR-AS-0001		
Acceptance Criteria - All prior items of this ITP have been complied with.		
Test/Inspection Frequency - Each Lot		
Inspection: John Holland - QR (R)	What does "QR(R)" mean? Is sign off by JH required here? Where is the final sign off for subcontractor?	
Records & Comments - All records loaded into the Work Lot System and Verified.		

Check all measurements are recorded and photos attached.

Attachments

