

# **NZC10013 - Waikeria Prison Development Project**

\*\*SAMPLE REPORT\*\* AES-NZ1005-STE-ITP-PMT-0024 - DCW Pipework Hydrostatic Pressure Test

## Report summary



Name	Status	Last Activity
**SAMPLE REPORT** AES-NZ1005-STE-ITP-PMT-0024 - DCW Pipework Hydrostatic Pre	essure Test - page 3	18 Apr 2023 8:45am pass

## \*\*SAMPLE REPORT\*\* AES-NZ1005-STE-ITP-PMT-0024 -DCW Pipework Hydrostatic Pressure Test



#### **1.0** MATERIAL COMPLIANCE

1.1	RDM & Consent Approval - C	PB Hold Point					
	Status	Pass	Michael Colin Simpson	18 Apr 2023 8:41am			
	CRITERIA - RDM approval tracker Consent approval tracker						
	Signature	Sign	Michael Colin Simpson	18 Apr 2023 8:41am			
	Signatory	СРВ					
1.2	General - CPB Hold Point						
	Status	Pass	Michael Colin Simpson	18 Apr 2023 8:41am			
	CRITERIA - For all materials, a certificate of compliance shall be provided to the Client Rep. before the materials are incorporated into the works.						
	Specifications & QA Documents Approved						
	Drawings are confirmed						
	• Equipment fit for purpose						
	Signature	Sign	Michael Colin Simpson	18 Apr 2023 8:41am			
	Signatory	СРВ					

#### **2.0** CONNECT PRESSURE PUMP TO DCW RING MAINS

2.1	Confirm Flushing & D	sinfection of Pipework - CPB Hold Point		
	Status	Pass	Michael Colin Simpson	18 Apr 2023 8:42am
	CRITERIA - 1. Air should entering building.	be removed at each building prior to the DCW water	er supply water entry assembly to prevent de	bris from

2.1	Confirm Flushing & Disinfec	tion of Pipework - CPB Hold Point				
	2. Ensure system sterilization completed.					
	3. Ensure TNK filtration is cleaned/ inspected if not isolated from test.					
	4. Ensure all screens/ strainer	s are cleaned/ inspected if not isolated from test.				
	Signature	Jigs	Michael Colin Simpson	18 Apr 2023 8:42am		
	Signatory	СРВ				
2.2	Accept delivery of pump to	site				
	Status	Pass	Michael Colin Simpson	18 Apr 2023 8:42am		
	CRITERIA - 5. Check pump is rated for pressure test					
	6. Check all supplied attachments are correct and in good order					
	7. Check fluid levels & fill as necessary					
2.3	Isolate: Mains water Storage Tanks					
	Status	Pass	Michael Colin Simpson	18 Apr 2023 8:42am		
	CRITERIA - 1. Check Mains water is isolated					
	2. Check Storage Tank is isolated					
2.4	Connect pump to DWC ring	mains				
	<u>Status</u>	Pass	Michael Colin Simpson	18 Apr 2023 8:42am		
	CRITERIA - Confirm connectio	ns are safe and correct				
2.5	Connect calibrated gauges for pressure test					
	Status	Pass	Michael Colin Simpson	18 Apr 2023 8:42am		
	CRITERIA - Confirm position is	correct, gauge is in good order for test & calibrated				
	Attach calibration certificate		Michael Colin Simpson	18 Apr 2023 8:42am		

### **3.0** HYDROSTATIC TEST

3.1	Fill DWC ring mains	s with domestic water				
	<u>Status</u>	Pass		Michael Colin Simpson	18 Apr 2023 8:42am	
	CRITERIA - Complete	ly fill closed loop system	with water releasing all air from the Taps at o	each Building		
3.2	Gradually increase system pressure to 1550kPa					
	Status	Pass		Michael Colin Simpson	18 Apr 2023 8:44am	
	CRITERIA - Slowly rai	se system pressure to 15	550kPa			
	• Checking for any si	gns of leaks or pressure	drops			
3.3	Stabilize 1550kPa p	ressure (START WITNES	SSED) - CPB/IR Hold Point			
	Status	Pass		Michael Colin Simpson	18 Apr 2023 8:42am	
	CRITERIA - Record ST	TART time & photograph	gauge			
	• All relevant parties	to witness starting press	sure of 1550kPa			
	Signature	Jig	L-	Michael Colin Simpson	18 Apr 2023 8:43am	
	Signatory	СРВ				
	Signature	Sig	$\sim$	Michael Colin Simpson	18 Apr 2023 8:43am	
	Signatory	IR				
	Attach photograph			Michael Colin Simpson	18 Apr 2023 8:42am	
3.4	Hold 1550kPa press	sure for 35min (END WI	TNESSED) - CPB/IR Hold Point			
	Status	Pass		Michael Colin Simpson	18 Apr 2023 8:43am	
	CRITERIA - Record FINISH time & photograph gauge All relevant parties to witness pressure of 1550kPa					
	Signature	Sig	h	Michael Colin Simpson	18 Apr 2023 8:43am	
	Signatory	СРВ				

3.4	Hold 1550kPa pressure for 3	5min (END WITNESSED) - CPB/IR Hold Point			
	Signature	J.g.	Michael Colin Simpson	18 Apr 2023 8:44am	
	Signatory	IR			
	Attach photograpgh		Michael Colin Simpson	18 Apr 2023 8:43am	
3.5	Pressure released or reduced for next test				
	Status	Pass	Michael Colin Simpson	18 Apr 2023 8:44am	
	CRITERIA - Supervisor to ensure energy (pressure) is only stored while under test				
3.6	Discharge pressure leave sys	stem in a safe state			
	<u>Status</u>	Pass	Michael Colin Simpson	18 Apr 2023 8:44am	
	CRITERIA - Discharge system p	ressure, ensure area is left in a safe state meeting site requirement			

### **4.0** COMPLETION RECORDS

4.1	Testing Results - CPB/IR Hold Point				
	Status	Pass	Michael Colin Simpson	18 Apr 2023 8:44am	
	CRITERIA - All pipework pressu	re test reports shall be provided			
	Signature	Sign	Michael Colin Simpson		
	Signatory	СРВ			
	Signature	Sign	Michael Colin Simpson	18 Apr 2023 8:44am	
	Signatory	IR			

## Attachments

