## CONSTRUCTION MANAGEMENT

### 3.0 SUBCONTRACTOR INSPECTION AND TEST PLAN (ITP) REVIEW

(One to be completed per ITP and retained in Subcontractor file)

	•	1	,		
Project		MQT - Medibank Fitout	Date:	24/03/202	23
Со	mpany Name	Express Interiors Pty Ltd			
Ac	tivity	Ceiling and Partition			
ITF	ITP Title Express ITP - No.1 Partition Walls		Checklists	Submitted	d? Yes 🗌 / No 🗌
Pro Re	oject Spec / v	Revision A			
	Requirement		Initial Review	Final Review	Comments
	Does the ITP:		Comply Y / N	Comply Y / N	
1	Reference proj Standards?	ect specifications and relevant Australian			
2		st all the required tests and inspections from cifications and Australian Standards?			
3		uirements from Lendlease's Project t and CiDD Alerts and Guidelines?			
4	Indicate respor				
5	Identify frequer verification, me				
6	Identify the typ Point, Review.				
7	Indicate the recompliance? (eChecklists, cer				
8	Has the ITP be for review, app Points/Witness				
9	Does the ITP in each type of in				
	Do the Inspect	Comply Y / N	Comply Y / N		
9		mbering, revision and space to record g number and revision?			
10	Reference the from the ITP?	ITP, and do line items reference line no's			
11	Identify who sh	ould be doing the inspection?			
12		of traceability and certificates of completion of sections of the works and for			



materials (where appropriate)?

# CONSTRUCTION MANAGEMENT

# SUBCONTRACTOR WORKS TO PROCEED EHS AND QUALITY CHECKLIST

	Name	Signature	Date
Lendlease Project Engineer			
Subcontractor Project Manager			
Lendlease Construction Manager			



ABN 13 082 094 960

38 Brindley Street Dandenong South VIC 3175 Phone: (03) 9793 9522

Email: express.interiors@bigpond.com

### **Inspection Plan Checklist**

#### **Partition Walls**

Doc.Ref-ITC-001-Rev1

#### **Project Information**

Name:	MQT – Medibank Fitout	Work:	All applicable
Address:	699 Collins Street, Docklands VIC 3008	Location:	
Head Contractor:	Lendlease	Drawing Ref. :	

#### **Details**

SAMPLES MATERIALS MEET SPECIFICATION REQUIREMENTS CHECK FOR DAMAGE	OK	N/A	DATE
CHECK FOR DAMAGE			
MATERIALS MEET SPECIFICATION REQUIREMENTS CHECK FOR DAMAGE			
CHECK FOR DAMAGE			
MAINTAIN SUITABLE STORAGE			
PREINSTALLATION OF SHEETS			
MECHANICAL SERVICES			
ELECTRICAL SERVICES			
COMMUNICATION SERVICES			
FIRE SERVICES			
HYDRAULIC SERVICES			
GAS PIPING			
FIRE STOPPING			
INSTALLATION REPORT			
Item 1: SET OUT			
Item 2: FURRING CHANNEL			
Item 3: METAL STUD WALL			
Item 4: NOGGINGS			
Item 5: DEFECTON HEAD			
Item 6: SERVICE CHECK FOR PRE-INSTALLATION			
Item 7: LININGS			
Item 8: CAULKING			
Item 9: INSULATION			
Item 10: STOPPING			
Item 11: SANDING			
Item 12: CLEAN UP			
Item 13: PATCHING			
Item 14: MATERIALS RECEIPT INSPECTION			
N.C.N. / C.A.R.			

#### **FINAL INSPECTION**

WITNESSED BY:	NAME	SIGNATURE	POSITION	DATE
SUBCONTRACTOR:			Foreman	
BUILDER:				
OTHER:				

#### **COMMENTS:**

<sup>\*</sup>This document will be provided to evidence compliance to applicable works

ABN 13 082 094 960

38 Brindley Street Dandenong South VIC 3175 Phone: (03) 9793 9522 Email: express.interiors@bigpond.com

Scope: Partition Walls	ITP Document No.: 1	Revision No. A	Date of Revision: 24/03/2023			
Project Name: Melbourne Quarter Tower	<ul> <li>Medibank Fitout</li> </ul>	Organization Name: Lendlease				
Project Address: 699 Collins Street, Docklands VIC 3008						
Prepared by						
Name: Austin Han	Position: Contract Administrator	Signature: A/	Date: 24/03/2023			
Approved by						
Name: Greg Edwards	Position: Construction Manager	Signature:	Date: 24/03/2023			

T 1	TD BY /A
Level:	Room No./Area:
Devel.	Room 100/11 cu

			W = Witness, HP = Hold Point, S =	Surveillance, R				
Item	Activity	Reference	Acceptance Criteria	Frequency	Frequency Verification Records/Comments	Inspection By		
		Documents				Subcontractor	Lendlease	Client
1	Set out walls	Architect drawings (MQT_ID series)  Architect Specification (MQT_IS_SPE 1)	Partition Plan and Partition Wall Details approved by Lendlease.  Architectural Specification – 0522 Partitions And Linings  Australian Standard: AS/NZS 4600:2005, AS/NS 1170:2002	Each location	Visual Checklist	S	S	
2	Furring channel to walls	Architect drawings (MQT_ID series)  Architect Specification (MQT_IS_SPE1)	Partition Plan and Partition Wall Details approved by Lendlease.  Architectural Specification – 0522 Partitions And Linings  Studco Wall design & installation manual Volume 3.2  Australian Standard: AS/NZS 4600:2005, AS/NS 1170:2002	Each location	Visual Checklist	S	S	
3	Metal stud wall frame	Architect drawings (MQT_ID series)	Partition Plan and Partition Wall Details approved by Lendlease.  Architectural Specification – 0522 Partitions And Linings	Each location	Visual Checklist	S	S	



ABN 13 082 094 960 38 Brindley Street Dandenong South VIC 3175 Phone: (03) 9793 9522

Email: express.interiors@bigpond.com



ABN 13 082 094 960 38 Brindley Street
Dandenong South VIC 3175

Phone: (03) 9793 9522

Email: express.interiors@bigpond.com

	Da	ndenong South VIC 317	5 Email: express.interiors@bigpond.com					
		Alerts and						
		Guidelines for						
		Fibre Cement						
		and Smoke						
		doors and						
		Baffle						
8	Caulking		Boral installation manual revision 2016	Each	Visual	S	S	
	Cuulking		Botal installation mandal levision 2010	location	Checklist		5	
			Australian Standard: AS 1530.4-2014,	100011011	Chickingt			
			AS4072.1-2005, AS1157-1972					
9	Check	Architect	Partition Plan and Partition Wall Details	Each	Visual	S	S	
	insulation in	drawings	approved by Lendlease.	location	Checklist	~	~	
	walls	(MQT_ID	approved by Leaders					
		series)	Batts Insulation Installation Guidelines					
		Architect	Architectural Specification – 0819 Insulation					
		Specification	and Barriers					
		(MQT_IS_SPE						
		_1)	Australian Standard: AS/NZS 4859:1 – 2018,					
		/	AS/NZS 1530.3 : 1999, AS/NZS1530 Part 1:					
			1994					
10	Stopping to	Refer to	Boral installation manual revision 2016.	Each	Visual	S	S	
	walls	Lendlease		location	Checklist			
		CiDD - Alerts	Australian Standard: AS/NZS 2589.1:1997					
		and Guidelines						
		for Setting						
		Compounds for						
		Plasterboard						
11	Sanding to walls		Boral installation manual revision 2016.	Each	Visual	S	S	
				location	Checklist			
			Australian Standard: AS/NZS 2589.1:1997					
12	Clean up		Waste all cleaned. Tools and materials placed	Each	Visual		R	
			well.	location	Checklist			
13	Check walls for	Architect	Partition Plan and Partition Wall Details	Each	Visual	S	S	
		drawings	approved by Lendlease.	location	Checklist			
			,					
		series)						
		Architect						
	1	Specification		1		1		
12	Clean up	and Guidelines for Setting Compounds for Plasterboard  Architect drawings (MQT_ID series)  Architect	Boral installation manual revision 2016.  Australian Standard: AS/NZS 2589.1:1997  Waste all cleaned. Tools and materials placed well.	Each location	Checklist  Visual  Checklist  Visual		R	



ABN 13 08		B Brindley Street andenong South VIC 3175	Phone: (03) 9793 9522 Email: express.interiors@bigpond.com	
		(MQT_IS_SPE _1)		
14	Materials Receipt Inspection	Refer to ITP No: 5 Incoming Goods		

Comments:	
Date of Inspection:	Carried out by:

<sup>\*</sup>This document will be provided to evidence compliance to applicable works