## FY 22- External maintenance & Painting project to 133~135 Kupe Street

Date: **6/07/2022** 

## SCOPE OF WORK

SCOPE O		Time	A	Camman'-	Duamanti:
<b>200</b> 201	Scaffolding Provide scaffolding, including planks and ladders to the height required to provided access to effect the safe execution of the work items within this scope of works including all provisional sum items.	Type L/S	Amount	Comments	Property
<b>300</b> 301	Provide temporary covers and temporary cladding to ensure weather protection and security during the construction process.	P/S			
400	Cladding Removal	l		l	
401	Remove all fittings and fixtures attached to the building. Allow for the removal and disposal of all downpipes, gutters and brackets	L/S			
402	Remove & dispose the UV corroded heat pump pipe works and trunking located in the north elevation & replace with new trunking & pipes	L/S			
403	Remove & reinstall AC condenser unit for painting	L/S			
404	Remove & dispose the Sky disk (including the coaxle cable) installed in the north elevation	P/S			
405	Remove & reinstate the fence attached to the sub floor wall for painting	L/S			
406	Remove & dispose/ reinstate the TV aerial	L/S			
407	Remove & dispose damaged/rotten timber weather boards, scribers, window facings and rusted metal soakers (for replacement refer SOW item 700)	L/S			
408	Remove ladder support fixed to weatherboard cladding	L/S			
409	Remove asbestos label for painting ( New label by others)	L/S			
500	External wall reinstatement		+		+
501	Remove and dispose of all wet and/or decayed timber framing, and mould affected material including insulation	P/S			
502	Replace removed framing with kiln dried H1.2 pressure treated Boron (pink) treated framing to the extent and dimensions as directed by the client.	P/S			
503	Apply Protim FrameSaver to all untreated and uncovered framing as instructed by the client. FrameSaver is to contain pink dye. A minimum of two (2) coats are to be applied by brush to all exposed timber frame surfaces.	P/S			
504	Argument wall bracing as per the NZS 3604 & other NZ codes	P/S			
600	External Windows and Doors				
601	Ease and adjust external windows as required.	P/S			
602	Remove rusted head flashings & replace with new powder coated Aluminium flashings.	P/S			
603	Remove & replace damaged window sashes	P/S			
604	Allow the supply and installation of new internal timber window sills, reveals, and architraves to windows and doors.	P/S			
605	Replace rusted /corroded window hardware including hinges, stays and latchets with similar hardware	P/S			
606	Remove and replace window putty	P/S			
607	Replace window seal to all window sashes	L/S			
608	Replace door seal to exterior doors	P/S			
609	Thoroughly prepare all exterior faces and exposed edges of the property's exterior doors, including all joinery, for a new paint finish in accordance with the paint manufacturers specification. Apply a three coats of semi gloss acrylic as specified and in accordance with the paint manufacturers recommendations. Paint is to be sourced from Resene.	L/S			
	Description	T		Commont	
700	Description Wall Cladding	<u>Type</u>		<u>Comments</u>	
701	Replace the weatherboard and associated soakers removed in item 400. Ensure the wall framing cavity remains open with suitable weather protection covers to allow for inspection. Install new H3.1 timber weatherboards and metal soakers.	P/S			
704	Rust treat & paint existing vent installed in the asbestos cladding	L/S			
705	Water blast exterior surfaces of the property prior to painting	L/S			
706	Thoroughly prepare all exterior faces and exposed edges of the property's exterior cladding, soffits, and facia and barge boards, for a new paint finish in accordance with the paint manufacturers specification. Apply a three coats of semi gloss acrylic as specified and in accordance with the paint manufacturers recommendations. Paint is to be sourced from Resene.	L/S			
706	Allow the supply and installation of new Marley PVC gutters and PVC downpipes with new associated brackets and supports. Allow the installation of gutters to all four elevations to connect to the existing outside storm water pipe	L/S			
707	Remove & replace damaged soffit, barge and fascia boards	P/S			

Subfloor Wall and Foundations  803  803  803  804  805  806  807  807  808  808  808  808  808	710	Replace loose exterior hose tap with new tap	L/S		1
Thoroughly prepare all exterior faces and exposed edges of the property's exterior subfloor wall cladding and entrance way stair and lobby for a new paint finish in accordance with he paint manufacturers specification. Apply a three coats of semi gloss acrylic as specified and in accordance with the paint manufacturers recommendations. Paint is to be sourced from Resene.  900 Decks, Handralis and Pergolas 902 Remove & reinsate timber deck in east & west elevation for scaffolding installation.  1000 Roof 1001 Wire brush, and wash all corroded roof elements including soil vent pipes. Apply Resene GP Metal Primer prior to application of primer and paint. Apply three coats of semi gloss acrylic as specified and in accordance with the paint manufacturers recommendations. Paint is to be sourced from Resene.  1002 Check & repair roof penerations 1003 Building Services 1100 Remove and reinstate plumbing pipes and fixtures as required or as directed by client 1102 Allow to inspect and make necessary repairs to electrical fittings, wiring and other electrical elements in the property 1103 Allow to install new extract fan to the exterior wall in the bath room 1100 Internal Fittings 1100 Internal Fittings 1100 Internal Rittchen/ 1100 Internal Kitchen/ 1100 Supply & install new electric extract fan through exterior wall with PVC cowl ( P/S ducting will be taken through ceiling)		replace lease sweller rises up min her up			
Thoroughly prepare all exterior faces and exposed edges of the property's exterior subfloor wall cladding and entrance way stair and lobby for a new paint finish in accordance with he paint manufacturers specification. Apply a three coats of semi gloss acrylic as specified and in accordance with the paint manufacturers recommendations. Paint is to be sourced from Resene.  900 Decks, Handralis and Pergolas 902 Remove & reinsate timber deck in east & west elevation for scaffolding installation.  1000 Roof 1001 Wire brush, and wash all corroded roof elements including soil vent pipes. Apply Resene GP Metal Primer prior to application of primer and paint. Apply three coats of semi gloss acrylic as specified and in accordance with the paint manufacturers recommendations. Paint is to be sourced from Resene.  1002 Check & repair roof penerations 1003 Building Services 1100 Remove and reinstate plumbing pipes and fixtures as required or as directed by client 1102 Allow to inspect and make necessary repairs to electrical fittings, wiring and other electrical elements in the property 1103 Allow to install new extract fan to the exterior wall in the bath room 1100 Internal Fittings 1100 Internal Fittings 1100 Internal Rittchen/ 1100 Internal Kitchen/ 1100 Supply & install new electric extract fan through exterior wall with PVC cowl ( P/S ducting will be taken through ceiling)	900	Subfloor Wall and Foundations			
Remove & reinsate timber deck in east & west elevation for scaffolding installation.  Roof  Wire brush, and wash all corroded roof elements including soil vent pipes. Apply Resene GP Metal Primer prior to application of primer and paint. Apply three coats of semi gloss acrylic as specified and in accordance with the paint manufacturers recommendations. Paint is to be sourced from Resene.  Dividing Services  Remove and reinstate plumbing pipes and fixtures as required or as directed by client  Allow to inspect and make necessary repairs to electrical fittings, wiring and other electrical elements in the property  Allow to install new extract fan to the exterior wall in the bath room  L/S  Internal Fittings  Internal Bathroom  Internal Bathroom  Internal Kitchen/  Supply & install new electric extract fan through exterior wall with PVC cowl ( ducting will be taken through ceiling)		Thoroughly prepare all exterior faces and exposed edges of the property's exterior subfloor wall cladding and entrance way stair and lobby for a new paint finish in accordance with the paint manufacturers specification. Apply a three coats of semi gloss acrylic as specified and in accordance with the paint manufacturers recommendations.	L/S		
Remove & reinsate timber deck in east & west elevation for scaffolding installation.  Roof  Wire brush, and wash all corroded roof elements including soil vent pipes. Apply Resene GP Metal Primer prior to application of primer and paint. Apply three coats of semi gloss acrylic as specified and in accordance with the paint manufacturers recommendations. Paint is to be sourced from Resene.  Dividing Services  Remove and reinstate plumbing pipes and fixtures as required or as directed by client  Allow to inspect and make necessary repairs to electrical fittings, wiring and other electrical elements in the property  Allow to install new extract fan to the exterior wall in the bath room  L/S  Internal Fittings  Internal Bathroom  Internal Bathroom  Internal Kitchen/  Supply & install new electric extract fan through exterior wall with PVC cowl ( ducting will be taken through ceiling)	200	Deale Handaile and Denseles			
installation.  Roof  Wire brush, and wash all corroded roof elements including soil vent pipes. Apply Resene GP Metal Primer prior to application of primer and paint. Apply three coats of semi gloss acrylic as specified and in accordance with the paint manufacturers recommendations. Paint is to be sourced from Resene.  1002 Check & repair roof penerations  P/S  1100 Building Services  Remove and reinstate plumbing pipes and fixtures as required or as directed by client  1101 Allow to inspect and make necessary repairs to electrical fittings, wiring and other electrical elements in the property  1103 Allow to install new extract fan to the exterior wall in the bath room  L/S  1200 Internal Fittings  1300 Internal Bathroom  1500 Internal Bathroom  1500 Internal Kitchen/ Supply & install new electric extract fan through exterior wall with PVC cowl ( ducting will be taken through ceiling)			D/C		
Wire brush, and wash all corroded roof elements including soil vent pipes. Apply Resene GP Metal Primer prior to application of primer and paint. Apply three coats of semi gloss acrylic as specified and in accordance with the paint manufacturers recommendations. Paint is to be sourced from Resene.  1002 Check & repair roof penerations P/S  1100 Building Services 1101 Remove and reinstate plumbing pipes and fixtures as required or as directed by client 1102 Allow to inspect and make necessary repairs to electrical fittings, wiring and other electrical elements in the property 1103 Allow to install new extract fan to the exterior wall in the bath room L/S  1200 Internal Fittings 1300 Internal General 1400 Internal Bathroom 1500 Internal Kitchen/ 1507 Supply & install new electric extract fan through exterior wall with PVC cowl ( ducting will be taken through ceiling)	902		P/3		
Wire brush, and wash all corroded roof elements including soil vent pipes. Apply Resene GP Metal Primer prior to application of primer and paint. Apply three coats of semi gloss acrylic as specified and in accordance with the paint manufacturers recommendations. Paint is to be sourced from Resene.  1002 Check & repair roof penerations P/S  1100 Building Services 1101 Remove and reinstate plumbing pipes and fixtures as required or as directed by client 1102 Allow to inspect and make necessary repairs to electrical fittings, wiring and other electrical elements in the property 1103 Allow to install new extract fan to the exterior wall in the bath room L/S  1200 Internal Fittings 1300 Internal General 1400 Internal Bathroom 1500 Internal Kitchen/ 1507 Supply & install new electric extract fan through exterior wall with PVC cowl ( ducting will be taken through ceiling)	1000	Post		+	+
Apply Resene GP Metal Primer prior to application of primer and paint. Apply three coats of semi gloss acrylic as specified and in accordance with the paint manufacturers recommendations. Paint is to be sourced from Resene.  1002 Check & repair roof penerations P/S  1100 Building Services 1101 Remove and reinstate plumbing pipes and fixtures as required or as directed by client 1102 Allow to inspect and make necessary repairs to electrical fittings, wiring and other electrical elements in the property 1103 Allow to install new extract fan to the exterior wall in the bath room L/S  1200 Internal Fittings 1300 Internal General 1400 Internal Bathroom 1500 Internal Kitchen/ 1507 Supply & install new electric extract fan through exterior wall with PVC cowl (P/S ducting will be taken through ceiling)			1./0		
1100 Building Services  1101 Remove and reinstate plumbing pipes and fixtures as required or as directed by client  1102 Allow to inspect and make necessary repairs to electrical fittings, wiring and other electrical elements in the property  1103 Allow to install new extract fan to the exterior wall in the bath room  1200 Internal Fittings  1300 Internal General  1400 Internal Bathroom  1500 Internal Kitchen/  Supply & install new electric extract fan through exterior wall with PVC cowl ( P/S ducting will be taken through ceiling)	1001	Apply Resene GP Metal Primer prior to application of primer and paint. Apply three coats of semi gloss acrylic as specified and in accordance with the paint	L/S		
1100 Building Services  1101 Remove and reinstate plumbing pipes and fixtures as required or as directed by client  1102 Allow to inspect and make necessary repairs to electrical fittings, wiring and other electrical elements in the property  1103 Allow to install new extract fan to the exterior wall in the bath room  1200 Internal Fittings  1300 Internal General  1400 Internal Bathroom  1500 Internal Kitchen/  Supply & install new electric extract fan through exterior wall with PVC cowl ( P/S ducting will be taken through ceiling)	1002	Check & repair roof penerations	P/S		
1101 Remove and reinstate plumbing pipes and fixtures as required or as directed by client  1102 Allow to inspect and make necessary repairs to electrical fittings, wiring and other electrical elements in the property  1103 Allow to install new extract fan to the exterior wall in the bath room  1200 Internal Fittings  1300 Internal General  1400 Internal Bathroom  1500 Internal Kitchen/  Supply & install new electric extract fan through exterior wall with PVC cowl ( p/S ducting will be taken through ceiling)		Onder a repair roof portorations	.,,		
1101 Remove and reinstate plumbing pipes and fixtures as required or as directed by client  1102 Allow to inspect and make necessary repairs to electrical fittings, wiring and other electrical elements in the property  1103 Allow to install new extract fan to the exterior wall in the bath room  1200 Internal Fittings  1300 Internal General  1400 Internal Bathroom  1500 Internal Kitchen/  Supply & install new electric extract fan through exterior wall with PVC cowl ( p/S ducting will be taken through ceiling)	1100	Building Services			
by client  Allow to inspect and make necessary repairs to electrical fittings, wiring and other electrical elements in the property  1103 Allow to install new extract fan to the exterior wall in the bath room  L/S  1200 Internal Fittings  1300 Internal General  1400 Internal Bathroom  1500 Internal Kitchen/  Supply & install new electric extract fan through exterior wall with PVC cowl ( P/S ducting will be taken through ceiling)			P/S		
other electrical elements in the property  1103 Allow to install new extract fan to the exterior wall in the bath room  L/S  1200 Internal Fittings  1300 Internal General  1400 Internal Bathroom  1500 Internal Kitchen/  1507 Supply & install new electric extract fan through exterior wall with PVC cowl ( ducting will be taken through ceiling)	1101		170		
1200 Internal Fittings  1300 Internal General  1400 Internal Bathroom  1500 Internal Kitchen/  1507 Supply & install new electric extract fan through exterior wall with PVC cowl ( ducting will be taken through ceiling)	1102		P/S		
1300 Internal General  1400 Internal Bathroom  1500 Internal Kitchen/  1507 Supply & install new electric extract fan through exterior wall with PVC cowl ( P/S ducting will be taken through ceiling)	1103	Allow to install new extract fan to the exterior wall in the bath room	L/S		
1300 Internal General  1400 Internal Bathroom  1500 Internal Kitchen/  1507 Supply & install new electric extract fan through exterior wall with PVC cowl ( P/S ducting will be taken through ceiling)					
1400 Internal Bathroom  1500 Internal Kitchen/ 1507 Supply & install new electric extract fan through exterior wall with PVC cowl ( P/S ducting will be taken through ceiling)	1200	Internal Fittings			
1400 Internal Bathroom  1500 Internal Kitchen/ 1507 Supply & install new electric extract fan through exterior wall with PVC cowl ( P/S ducting will be taken through ceiling)	1300	Internal General		+	
1500 Internal Kitchen/ 1507 Supply & install new electric extract fan through exterior wall with PVC cowl ( ducting will be taken through ceiling)	1000	THE CONTROL		ı	
1507 Supply & install new electric extract fan through exterior wall with PVC cowl ( P/S ducting will be taken through ceiling)	1400	Internal Bathroom			
1507 Supply & install new electric extract fan through exterior wall with PVC cowl ( P/S ducting will be taken through ceiling)	1500	Internal Kitchen/			
1600 Internal Living Room L/S		Supply & install new electric extract fan through exterior wall with PVC cowl (	P/S		
1600 Internal Living Room L/S					
	1600	Internal Living Room	L/S		

	Description	Type	Amount	Comments	
1800	External Works				
1802	Replace grates over gully traps where required due to damage or dilapidation.	P/S			
1803	Install casing over the properties electrical earth rod.	P/S			
1804	External drainage & retainng wall	P/S			
TOTAL:			0.00	0.00	
	·		_	_	