F.I.R.S.T. CHECKLIST #1 LOAD / UNLOAD FROM VAN

- Robot computer and charger (in lockbox in van)
- o -main cart
- o -batteries toolbox
- o -first aid, tape, cclamp and block of wood toolbox
- o -dewalt toolboxes 1, 2, 3
- o -empty toolbox
- o -yellow tote(have drill chargers, soldering station, wires)
- o -gray tote
- -game pieces tote(have important book)
- o -BIG toolcase
- o -robot
- o -extra hang thing
- o -Mr abletts tent
- o -spare bumpers
- o -soft tool box

GENERAL NOTES:

3 padlocks in top compartment of BIG toolcase NEED SOMETHING TO CUT THING DOWN TO SIZE Is the new rope in one of the toolboxes?

F.I.R.S.T. CHECKLIST #2 GRAY TOTE (MECHANICAL)

```
2 %" churro
0
0
       white 4" wheels(x6)
0
       blue 4" wheels(x7)
0
       pneumatic tubing 1/4" black
0 white zip ties(x100)
0 3/16" elastic tubing; yellow and orange
0 3/4" wide velcro tape
0 1" wide velcro tape
0 1/2" foam tape
0 rubber grommits large and small
0 ½ of a nylon cutting board
0 24" aluminum slide rail body
0 linear slides for \Lambda, (x2)
0 red bumper material (x2) pieces
0 blue bumper material (x6) pieces
_____
0 3 ½" x ¾" x 2" 90 degree brackets (x4)
0 2" x 4" flat bracket w/ 2 1 1/8" holes
0 2" x 3/4" x 2 1/4" 90 degree brackets w/ hexagonal holes (x4)
0 1 x 3/4 x 1 90 degree brackets (x4)
                                                                                Ziploc Bag
0 Bumper brackets (x4)
O Scrap base unsymmetrical c-channel bracket (x2)
0 2 x 1 x 3/4 brackets (x2)
0 \( \gamma_8 \text{ x 14 } \frac{3}{8} \text{ piano hinge} \)
0 small 1" velcro tape
0 ~4' #35 chain
0 ½" velcro tape
0 smooth rubbery tape
0 1x each of 12", 14", 16" surgical tubing
0 "scotch weld" glue
                                                                         Law logistics
0 "scotch weld" instant adhesive tube
0 vulcan constant-force spring
0 versaplanetary gearbox set (x2)
0 pneumatic tee joint (x2)
0 pneumatic brass adapter M to F
       pneumatic brass plug
```

CHECKLIST 2 CONTINUED

```
0 5/8 " x 24" steel axle(x2)
0 40" cable tray (flexible)
0 plastic flanged bushings (x2)
0 plastic ½" bushings (x2)
0 plastic flange bearings (x2)
0 rod end (plastic) (x2)
                                                                      IGUS bag
0 %" plastic washer (x2)
0 Pillow block mount bracket top
0 pillow block mount bracket bottom (x2)
0 lazy susan bearing
0 1/2 'nylon pillow block(x2)
       3/8" nylon pillow block (x2)
0
0 2" rubber wheels (x6)
0 blue rubber wheel(round insert)
0 orange rubber wheel( hex insert)
0 green rubber wheel
0 black rubber wheel
0 1/8" x 21 1/8" steel tube (one end threaded) (IN EXTERNAL HANG, NOT IN TOTE)
0 1' black hex axle
0 8" black hex axle
       1/2" x 23 1/2" ready rod
                                          In labelled Box
0 ½" nuts (x6)
       1/2" washers (x2)
0 ½' flanged bearing (x8)
0 intake sys hardware kit
0 versahub ½" hex
```

F.I.R.S.T. CHECKLIST #3 YELLOW TOTE (ELECTRICAL)

- 0 Logitech Joystick
- 0 xbox 360 controller
- 0 HS-322HD HITec servo(x2)
- 0 Startech USB to Ethernet adapter
- 0 limit switches
- 0 Spark motor Controller bolts(x4)
- 0 Rev Robotics Servo power module
- 0 Backup power charger
- 0 Talon SRX motor controller
- 0 lifecam camera
- 0 Bag of red and black 8gage and other unassorted wire
- 0 bag of braided red/orange/black wires
- 0 bx of RWB wires(like vex wires)
- 0 Bag of extra/supplimentary pieces for sonic shifter
- 0 Big copper wire(x2)
- 0 RWB Big y cable
- 0 fuse/connectors(random)