%%

Table of Contents

Dan Otieno. CPE 381-01. Homework 4 - Q1. 03/28/2023.

```
clear all; clf
wmax=20;

n1=[1 0 4*pi^2]; d1= [1 2 (1.25+4*pi^2) (0.25+4*pi^2)];
figure(1)
[w,Hm,Ha]=freqresp_s(n1,d1,wmax);

n2=[1 -3 3+4*pi^2 -(1+4*pi^2)]; d2=[1 3 3+4*pi^2 (1+4*pi^2)];
figure(2)
[w,Hm,Ha]=freqresp_s(n2,d2,wmax);

n3=[1 -1]; d3=[1 3 3+4*pi^2 (1+4*pi^2)];
figure(3)
[w,Hm,Ha]=freqresp_s(n3,d3,wmax);
```

%%

```
function [w,Hm,Ha]=freqresp_s(b,a,wmax)
w=0:0.01:wmax;
H=freqs(b,a,w);
Hm=abs(H);
Ha=angle(H)*180/pi;
subplot(311)
plot(w,Hm)
axis([0 wmax 0 1.1*max(Hm)])
ylabel('|H(j \omega)|')
grid
xlabel('\Omega')
title(' Magnitude response')
subplot(312)
plot(w,Ha)
axis([0 wmax 1.1*min(Ha) 1.1*max(Ha)])
ylabel('< H(j \omega)')</pre>
xlabel('\Omega')
title(' Phase response')
grid
subplot(313)
splane(b,a)
title('Poles/Zeros')
grid
end
>>>> Zeros <<<<
z =
   0.0000 + 6.2832i
   0.0000 - 6.2832i
>>>> Poles <<<<
p =
  -0.5000 + 6.2832i
  -0.5000 - 6.2832i
  -1.0000 + 0.0000i
>>>> Zeros <<<<
z =
   1.0000 + 6.2832i
   1.0000 - 6.2832i
```

1.0000 + 0.0000i

>>>> Poles <<<<

p =

-1.0000 + 6.2832i

-1.0000 - 6.2832i

-1.0000 + 0.0000i

>>>> Zeros <<<<

z =

1


>>>> Poles <<<<


p =


-1.0000 + 6.2832i

-1.0000 - 6.2832i

-1.0000 + 0.0000i







%%

%%

Published with MATLAB® R2023a