

Mechanical Drawing

ME-2412

Instructor- Arafath Al Fahim

Orthographic Projection

68

0




Fig. P3.11

Orthographic Projection






Fig. P3.2

Orthographic Projection



Orthographic Projection



Orthographic Projection

Prob. P3.58: Draw top, front and right side views of the holder as shown in Fig. P3.58.





Fig. P3.58

Prob. P3.59: Draw the top, front and right side views of the support as shown in Fig. P3.59.







Fig. P3.59


Orthographic Projection

74
74
Prob. P3.58: Draw top, front and right side views of the holder as shown in Fig. P3.58.



Orthographic Projection

p. P3.60: Draw top, front and right side views of the bracket as shown in Fig. P3.60.



Orthographic Projection






Fig P3.5


Orthographic Projection



Sectional Drawing




Practice






PowerDirector

Sectional Views



Sectional Views





Full
Sectional Object




Engineering Graphics



Ribs



- Section lines are not placed in the ribs even if they are cut by the cutting plane.
- Otherwise these would give the false impression that the part is thicker than it really is.



Draw Full Section Front View of the given object.




PowerDirector

Ribs




- Section lines are not placed in the ribs even if they are cut by the cutting plane.
- Otherwise these would give the false impression that the part is thicker than it really is.



Ribs




- Section lines are not placed in the ribs even if they are cut by the cutting plane.
- Otherwise these would give the false impression that the part is thicker than it really is.



Ribs




- Section lines are not placed in the ribs even if they are cut by the cutting plane.
- Otherwise these would give the false impression that the part is thicker than it really is.



Ribs

- Section lines are not placed in the ribs even if they are cut by the cutting plane.
- Otherwise these would give the false impression that the part is thicker than it really is.



Sectional Drawing




Figure 5.3.1: Object with Cutting Plane through Mid-Section






Figure 5.3.2: Section after Cutting

Sectional Drawing




Top View




Front Sectional View


Sectional Drawing




Sectional Drawing




Sectional Drawing



Sectional Drawing



Sectional Drawing



Sectional Drawing

Prob. 4.3: Draw the top view and a suitable sectional view of the bearing retainer shown in Fig. P4.3.







Fig. P4.3

Isometric Drawing






Isometric Drawing



Autocad Drawing



Autocad Drawing

