


Pressure/Z calibration: compare real line darkness on your tool


light Z=10.65, F=11500




soft-mid: Z=10.90, F=10000



mid: Z=11.15, F=8800



dark-mid: Z=11.45, F=7800



dark: Z=11.75, F=6800

