

Technical drawing of a stepped shaft (Figure 1.10). The drawing shows a shaft with three steps. The dimensions are as follows:

- Overall length: 100
- Overall diameter: $\phi 22$
- Step 1 (left): Diameter $\phi 18$, length 3
- Step 2 (middle): Diameter $\phi 13$, length 4
- Step 3 (right): Diameter $\phi 20$, length 10

The drawing includes a cross-section view and a side view. The cross-section view shows the stepped profile of the shaft. The side view shows the shaft with a central hole of diameter $\phi 10$ and a length of 10. The dimensions are indicated by arrows and numbers.

						М400520007					
						Втулка	Лист		Масса	Масштаб	
Изм. Лист	№ докум		Подп.	Дата						5:1	
Разработ	Сухорев ДИ										
Грав	Гузанина										
Г.контр.											
							Лист		Листов		1
Н.контр.						Сталь 40 ГОСТ 1050-74	IT-515-3				
И.б											