```
🗋 📂 📓 🔘 🏇 🤼 🗈 🕪 👨
[ dh11 ] ×
  1 from machine import Pin
    from time import sleep
  3 import dht
 4
 5 d= dht.DHT11(Pin(14))
 6 while True:
 7
            sleep(3)
 8
            d.measure()
            temp = d.temperature()
 9
            hum = d.humidity()
 10
            print('Temperature: %2.2f C' %temp)
 11
 12
            print('Humidity: %2.2f %%' %hum)
```

```
Console ×
 Temperature: 17.00 C
 Humidity: 22.00 %
 Temperature: 18.00 C
 Humidity: 37.00 %
 Temperature: 18.00 C
 Humidity: 38.00 %
 Temperature: 18.00 C
 Humidity: 40.00 %
 Temperature: 18.00 C
 Humidity: 24.00 %
 Temperature: 22.00 C
 Humidity: 26.00 %
 Temperature: 22.00 C
 Humidity: 31.00 %
 Temperature: 23.00 C
 Humidity: 30.00 %
 Temperature: 23.00 C
 Humidity: 34.00 %
 Temperature: 23.00 C
 Humidity: 30.00 %
```