

 Technical Report:
 96243620301
 JANUARY 06, 2025

 Date Received:
 DECEMBER 27, 2024
 Page 1 of 6

DAI VIET CO., LTD

NO. 276/19/13 TRAN HUNG DAO STREET, DONG B QUARTER, DONG HOA WARD, DI AN CITY, BINH DUONG PROVINCE, VIETNAM.

TWIN LOFT BED WITH DRAWER AND SHELVES Sample Description: Vendor: DAI VIET CO., LTD Sample Size: Manufacturer: VPN: DAI VIET CO., LTD **GIGACLOUD** SKN/SKU No.: Buyer: WF314591/WF314592 Agent: Labeled Age Grade: PO No.: V346VDY20241030LE Appropriate Age Grade: Ref #: Client Specified Age Grade: Country of Origin: VIETNAM Tested Age Grade: Assortment No.: UPC Code: Department No.: Phase of Production: Item#: Date of Production: Color: GREY/ WHITE Program: 203*108*160 Model/Style#: Previous No: 96243410261 Country of Destination: USA

TEST PROPERTY	PASS	FAIL	DATA	N/A	Remark
CPSIA Total lead content in Surface Coating	Х				
CPSIA Total Lead Content in Substrate Materials	Х				
15 U.S.C 1278a Total Lead Content	Х				
16 CFR 1213 Bunk Beds	Х				
16 CFR 1513 Requirements for Bunk Beds	Х				

X

Note(s):

- This report includes the test result(s) which was conducted & reviewed by Analytical department.
- The Chemical test following reports listed:

ASTM F1427-21e1 Bunk Beds

No.	Tested component:	Chemical test	Reference report	Report issued date
1	White coating/Wood	Lead	96241420405	JUNE 03, 2024



DAI VIET CO., LTD Technical Report: 96243620301 JANUARY 06, 2025 Page 2 of 6

If there is any question regarding this report, please contact the following lab personnel:

Administrative inquiries, please contact:

Primary Contact: Elise Vo, Tel: 84-028-37421-604 ~ 6, Ext: 394; email: elise.vo@bureauveritas.com Back-up Contact: Cynthia Vuong, Tel: 848-37421-604 ~ 6, Ext: 641; email: cynthia.vuong@bureauveritas.com

Technical inquiries, please contact:

Primary Contact: Terry Nguyen, Tel: 84-028-37421-604 ~ 6, Ext: 355; email: terry.nguyen@bureauveritas.com Back-up Contact: Louis Tran, Tel: 84-028-37421-604 ~ 6, Ext: 339; email: louis.tran@bureauveritas.com

BUREAU VERITAS CONSUMER PRODUCTS SERVICES (VN) LTD.

TERRY NGUYEN

LAB MANAGER - HARDLINE, TOYS & JUVENILE PRODUCTS DIVISION



DAI VIET CO., LTD Technical Report: **96243620301** JANUARY 06, 2025 Page 3 of 6

REQUIREMENTS FOR BUNK BEDS (FHSA, Title 16, CFR, Part 1213 & 1513)

Section	Description	Results
1213.3	Requirements	
1513.3		
1213.3(a) 1513.3(a)	Guardrails	
1213.3(a)(1) 1513.3(a)(1)	Two guardrails required if bed is > 30 inches from ground	М
1213.3(a)(2) 1513.3(a)(2)	One guardrail shall be continuous	М
1213.3(a)(3) 1513.3(a)(3)	No greater than 15 inches between either end	М
1213.3(a)(4) 1513.3(a)(4)	Bunk Beds with ladder, continuous guardrail on other side	М
1213.3(a)(5) 1513.3(a)(5)	Guardrails attached so they cannot be removed without releasing a device	М
1213.3(a)(6) 1513.3(a)(6)	The upper edge shall be no less than 5 inches above top surface	М
1213.3(a)(7) 1513.3(a)(7)	No openings in the structure between lower edge and underside	М
1213.3(b) 1513.3(b)	Bed End Structures	
1213.3(b)(1) 1513.3(b)(1)	The upper edge of end structure shall be at least 5 inches above mattress	М
1213.3(b)(2) 1513.3(b)(2)	No openings in the structure above foundation of the upper bunk that permits passage of the wedge block	М
1213.3(b)(3) 1513.3(b)(3)	Tested in accordance with Section 1213.4(c)	М
1213.3(b)(4) 1513.3(b)(4)	Neck entrapment requirements of Section 1213.4(c)(3)	М
1213.5 1513.5	Marking and Labeling	
1213.5(a) 1513.5(a)	Permanent label with name and address, model # and date code	М
1213.5(b) 1513.5(b)	Permanent Warning Label placement	М
1213.6 1513.6	Instructions	
1213.6(a) 1513.6(a)	Size of mattress and foundation	М
1213.6(b) 1513.6(b)	Safety Warning	-
1213.6(b)(1) 1513.6(b)(1)	Do not allow children under 6 years of age to use the upper bunk	М
1213.6(b)(2) 1513.6(b)(2)	Use guardrails on both sides of the upper bunk	М



DAI VIET CO., LTD Technical Report: **96243620301** JANUARY 06, 2025 Page 4 of 6

1213.6(b)(3)	Prohibit horseplay on or under beds	М
1513.6(b)(3)		
1213.6(b)(4)	Prohibit more than one person on upper bunk	М
1513.6(b)(4)		
1213.6(b)(5)	Use ladder for entering or leaving upper bunk	М
1513.6(b)(5)		
1213.6(b)(6)	If the bed is placed against a wall, use full length guardrail along wall	М
1513.6(b)(6)		

M = Meet NM = Not Meet NA = Not Applicable R = Refer to Comment Section



DAI VIET CO., LTD Technical Report: 96243620301 JANUARY 06, 2025 Page 5 of 6

RESULT(S):

STANDARD CONSUMER SAFETY SPECIFICATION FOR BUNK BEDS (ASTM F1427-21e1)

Section	Requirement	Result	
4	Performance Requirements		
4.1	Vertical Protrusions	-	
4.1.1	Vertical protrusions along the top inside surface	М	
4.1.2	Cap used along the top surface of upper bunk	NA	
4.2	Fit of Top Bed to Bottom Bed	М	
4.3	Mattress and Foundation Size and Fit (Top Bed)	М	
4.4	Mattress Size and Fit (Lower Foundation)	М	
4.5	Upper and Lower Foundation Support Systems	-	
4.5.1	Horizontal position of the mattress and the foundation	М	
4.5.2	Utilized event cross-members	М	
4.5.3	Release of positive fastening devices or use of hand tools	М	
4.5.4	Static load for the foundation support system	М	
4.6	Side Rails	-	
4.6.1	Bolt-On Side Rails	М	
4.6.2	Hook-On Side Rails	NA	
4.6.3	Side rail attachments	М	
4.7	Guardrails	-	
4.7.1	Presence of guardrails	М	
4.7.2	Requirement of attachment	М	
4.7.3	Requirement of height of the upper edge above the sleeping surface	М	
4.7.4	Opening of the guardrail	М	
4.7.5	Opening between the either end of the guardrail and the bed end structure	М	
4.8	Bed Structure	-	
4.8.1	The upper edge of the upper bunk end structures	М	
4.8.2	Openings in the rigid end structures of the upper bunk	М	
4.8.3	Openings in the end structures of the lower bunk	М	
4.8.4	Neck entrapment requirement of all portions of the boundary of any opening of the lower bunk end structure	М	
4.9	Ladders	-	
4.9.1	Presence of ladder	М	
4.9.2	Dimension requirement of ladder	М	
4.9.3	Openings between ladder step and upper bunk boundary	М	
4.9.4	Gaps between edge of mattress and interior vertical stile	М	
4.10	Metal beds: frame and fastenings	NA	
6	Marking and Labeling	М	
7	Instructional Literature	М	



DAI VIET CO., LTD Technical Report: **96243620301** JANUARY 06, 2025 Page 6 of 6



