

# **ASSEMBLY INSTRUCTION**



IMPORTANT: PLEASE READ INSTRUCTION BEFORE STARING THE ASSEMBLY

# PLEASE DO NOT RETURN TO STORE



Please do not return this product to the retailer!!
We are able to assist you in ANY way

If you find that you have any trouble with assembly or missing or damaged parts please contact the seller.


## **Before Installation**

#### Important-Please read these instructions fully before starting the assembly

Thank you for purchasing this quality product.Be sure to check all packing materials carefully for small parts, which may have come loose inside the carton during shipment. Identify and count all items according to the PARTS LIST and/or HARDWARE LIST shown below. Check you have all the components and tools listed on the following pages.


- •We recommend that you assemble this product with the assistance of another person; this will make the assembly easier, and will help eliminate damage to the product or injury to persons during assembly.
- •Please do not over tighten screws or bolts until the assembly is completed.
- •Keep children and animal away from the work area, small parts could choke if swallowed. Please put all parts on a non-abrasive floor before assembly, and follow the assembly steps to assemble your newly purchased product correctly and efficiently.

#### Hinge installation method




#### 1. Screw installation method

When the screw is installed, please keep it in line with the board, and do not tighten it too tightly




#### 2. Check the direction of the nut


This direction of the marked nutis consistent with the direction in which the scre is inserted





#### 3. Installation on thr board with fixing screws





#### 3. Rotate slowlyuntil it stops

















6 - x1 1 - x4 11 - x1 16 - x1 21 - x2 2 - x1 17 - x4 22 - x1 7 - x1 12 - x1 3 - x1 23 - x1 8 - x1 13 - x1 18 - x2 9 - x1 4 - x1 14 - x1 19 - x1 5 - x1 10 - x1 15 - x1 20 - x2

### HARDWARE







B SCREW & METAL LOCK X52







С	SCREW	х4
---	-------	----



E HANDLE X2








K	SCREW	х3
---	-------	----








M SOCKET XI





# Step7 В 11 Step8 B 16 Step9

# Step10 Ε 18 Step11 0 Step12 18 9

