


# INSTRUCTION



30 min



360kg



## HARDWARE LIST

| CODE | PARTS | QTY.            |
|------|-------|-----------------|
| A    |       | M6x67mm<br>2PCS |
| B    |       | M8x95mm<br>2PCS |
| C    |       | M8x50mm<br>4PCS |
| D    |       | M8x50mm<br>4PCS |
| E    |       | M8x20mm<br>8PCS |
| F    |       | 1PC             |
| H    |       | 1PC             |
| I    |       | 2PCS            |
| J    |       | 4PCS            |


### PARTS LIST

| CODE | PARTS | QTY. |
|------|-------|------|
| #1   |       | X2   |
| #2   |       | X1   |
| #3   |       | X1   |
| #4   |       | X1   |
| #5   |       | X1   |
| #6   |       | X1   |
| #7   |       | X1   |
| #8   |       | X1   |
| #9   |       | X4   |
| #10  |       | X1   |
| #11  |       | X1   |


### PARTS LIST





| CODE  | PARTS | QTY. |
|-------|-------|------|
| #12   |       | X1   |
| #13   |       | X1   |
| #13-1 |       | X1   |
| #14   |       | X2   |
| #15   |       | X1   |
| #16   |       | X1   |
| #17   |       | X1   |
| #18   |       | X2   |
| #19   |       | X2   |
| #20   |       | X2   |
| #21   |       | X1   |
| #22   |       | X1   |
| #23   |       | X2   |
| #24   |       | X2   |

1




2







**7**




**8**




**9**




**10**




**11**




**12**



13



14



**15**

