

REPORT

Technical Report: (8524)340-0106(Revised)

Page 1 of 6 December 24, 2024





TEST REPORT

FU'AN MUSIC DANCE ELECTRICAL APPLIANCE LAB LOCATION: SHENZHEN

CO., LTD

HUIFENG ROAD. JINYUAN, CHENGYANG,

FUAN, NINGDE, FUJAIN, CHINA.

LAB NUMBER:

(8524)340-0106(Revised)

ATTN: Zhenyu Lin

CC: 2208675500@qq.com

DATE IN: December 05, 2024

MOD. LOG IN: December 20, 2024

DATE OUT: December 24, 2024

REVISED DATE: December 25, 2024

WORKING DAYS: 3 PAGE: 2 OF 6

	OVERALL RATING	
PASS	_	X
FAIL	_	_
DATA	_	
	-	

TESTING FOR UPHOLSTERED FURNITURE FLAMMABILITY FLAMMABILITY OF COVER FABRIC

Sample Description:	MASSAGE CHAIR	
Manufacturer:	/ P.O. No.:	/
Buyer:	/ Style:	MODEL#: TOK-603,
	•	TOK-601, TOK-602,
		TOK-605, TOK-606,
		TOK-607, TOK-608,
		TOK-609, TOK-610,
		TOK-989, TOK-B02,
		TOK-B01, TOK-B03,
		TOK-B05, TOK-B06,
		TOK-B07, TOK-B08,
		TOK-B09, TOK-B10,
		6801, 6802, 6803, 6805,
		6806, 6807, 6808, 6809,
		TOK-D01, TOK-D02,
		TOK-D03, TOK-D05,
		TOK-D06, TOK-D07,
		TOK-D08, TOK-D09,
		TOK-D10
Country of Origin:	Country of Destination:	/
Color:	/ SKU Number:	/
Re-test:	Yes: No: X Charge Vendor:	Yes: X No:
Previous Report No.:		



EXECUTIVE SUMMARY:

1. The submitted sample(s) MEET(s) below test requirement: (PASS)

Evaluation	Citation / Method	Criteria	Result	Rating
Upholstered furniture flammability	16 CFR 1640	Upholstered furniture must comply with the flammability requirements of California Technical Bulletin 117-2013. For submission received before June 25, 2021 non-compliance with this requirement will be rated as DATA. For submission received on or after June 25, 2021, non-compliance will be rated as FAIL.	M Only performed on cover fabric	PASS
Flammability of cover fabric	California Technical Bulletin 117-2013 Section 1	Shall not develop a specified char length, transition to open flaming and smoke. Note 1: Upholstery cover fabrics that fail the cover fabric test described in Section 1 can be used in upholstered furniture if a barrier (interliner) material that passes this test method is used. When a barrier is required, the barrier material must cover all sides and top of the seating cushion(s). Exceptions: Non-reversible and non-detachable seating cushions do not require the use of the barrier material on the underside of the seating cushion. Note 2: For cover fabrics that pass this section, the first layer of filling materials located below the cover fabric shall all meet the requirements of Section 3.	M See result table	PASS

Remark(s):

- 1. No protocol was enclosed for test results.
- 2. The tests covered in this report were conducted per client's request.
- 3. (*)This report is amendment of and supersedes the previous (8524)340-01106 dated December 24, 2024.



NOTE: If there are questions or concerns regarding above report, please contact the appropriate lab persons.

General Enquiries: Rebecca Huang/ Catelyn Lai

(+86)755-32980232 / 32980216 Rebecca.huang@bureauveritas.com Catelyn.lai@bureauveritas.com

BUREAU VERITAS SHENZHEN CO., LTD

Supr

Sure Fu

SENIOR TECHNICAL MANAGER

HARDLINES DIVISION



RESULT:

TEST RESULT

Flammability of cover fabric test

Test Method : California Technical Bulletin CA TB 117-2013 section I

Tested Item(s) : cover

RESULT FOR INITIAL TEST:			
SPECIMEN	TRANSITION TO OPEN FLAMING	SMOLDERING	CHAR LENGTH (IN)
1	N	N	0.5
2	N	N	0.4
3	N	N	0.4

OVERALL RATING:	PASS	

Note / Key:

Y=Yes DATA = Record data only N=No NA = Not Applicable P=Pass NR= Not requested F=Fail NT=Not Tested





END OF REPORT