

Converter q-axis current states (device base, actual run)
IBR30 i_q
IBR32 i_q
IBR33 i_q
IBR34 i_q
IBR35 i_q
IBR36 i_q
IBR37 i_q
IBR38 i_q
IBR39 i_q
i_q (pu dev)
Time (s)