
(a) Common level
promotion = 0.85
Success rate
initial position error (m)
Base, 10 mm / 0.10 rad
Full, 10 mm / 0.10 rad
(b) Common level
promotion = 0.85
initial orientation error (rad)
Base, 10 mm / 0.10 rad
Full, 10 mm / 0.10 rad
(c) Strict levels
promotion = 0.85
Success rate
initial position error (m)
Full, 10 mm / 0.10 rad
Full, 1 mm / 0.025 rad
M3, 1 mm / 0.10 rad
(d) Strict levels
promotion = 0.85
initial orientation error (rad)
Full, 10 mm / 0.10 rad
Full, 1 mm / 0.025 rad
M3, 1 mm / 0.10 rad