


Real Axis

$$G_{OL}(z) = \frac{z - 1}{z(z - 0.5)}$$



Real Axis

