




铁头山羊STM32教程

[串口]

3.1. 通信协议


0000 0001 高 1 低 1 一字节


高电平(空闲) 起 [1 0 0 0 0 0 0 0] 停 空闲




Tx: Transmit 数据发送引脚

Rx: Receive 数据接收引脚






例子1: 通过串口发送十进制数字27



例子2: 发送字符串 "Hello"

01001000 01100101 01101100 01101111
 ASCII码 H=0x48, e=0x65, l=0x6c, o=0x6f






无 8 9
有 0 1

起 00 ... 06 07 停 1字节 ✓


(起 00 ... 06 07 停 不是1字节

起 (00 ... 06 07 08) 停 多于1个字节


起 00 ... 06 07 08 停 1字节 ✓



- 奇校验 要求数据位中有奇数个1
- 偶校验 要求数据位中有偶数个1



发送方发送85(0101 0101)



接收方

