


Stress Amplitude vs Number of Cycles

Stress amplitude (MPa)

1200
1150
1100
1050
1000
950
900
850
800
750



Number of cycles

0 2 4 6 8 10 12