	1	2	3			4	
A							A
	V5+_CORE Modify RC00	ist ist	RC00				
В	1: IO修改 PB6//	MUV5管理图,进行细节修改 PB7 将这些IO释放为普通GPIO使用,原来是POWER切换芯片的ABC标 RE_GPIO1,PB7=IO_SPARE_GPIO2,PB12=IO_SPARE_GPIO6	2019-1-26	Check the FMUV5 schemati Modify the io PB6/PB7 pins			В
	2: 移动80P连接	连接器,让定义分类更集中和规范 5器位置,因为定义已不兼容,所以让结构上与之前的不兼容,避免	A Move the c		not compatible with v5 (to prevent fa	alse connections.)	
	3: 修议内部IM	U扩展总线为SPI6,之前的为SPI5	Modify the	e internal IMU expansion bus to	SPI6 instead of SPI5		
С	2019-2-25 1:修改CAN芯,	310位置,避免TF卡槽导致罗盘干扰的问题	2019-2-25	odify the DSM&SBUS output a odify the S pin pull-up of the C	nd PPM input to separate them into AN chip	two separate interfaces	С
D							D
	1	2	3			4	





















