

AMD ROCm™ v4.3.1 Point Release Notes

Revision 08027

Issue Date: August 2021

DISCLAIMER

The information contained herein is for informational purposes only, and is subject to change without notice. In addition, any stated support is planned and is also subject to change. While every precaution has been taken in the preparation of this document, it may contain technical inaccuracies, omissions and typographical errors, and AMD is under no obligation to update or otherwise correct this information. Advanced Micro Devices, Inc. makes no representations or warranties with respect to the accuracy or completeness of the contents of this document, and assumes no liability of any kind, including the implied warranties of noninfringement, merchantability or fitness for particular purposes, with respect to the operation or use of AMD hardware, software or other products described herein. No license, including implied or arising by estoppel, to any intellectual property rights is granted by this document. Terms and limitations applicable to the purchase or use of AMD's products are as set forth in a signed agreement between the parties or in AMD's Standard Terms and Conditions of Sale.

- * AMD®, the AMD Arrow logo, AMD InstinctTM, RadeonTM, ROCm® and combinations
- * thereof are trademarks of Advanced Micro Devices, Inc. Linux® is the registered trademark of Linus Torvalds in the U.S. and other countries.
- * PCIe® is a registered trademark of PCI-SIG Corporation. Other product names used in this publication are for identification purposes only and may be trademarks of their respective companies.

	ı
--	---

[This page is left blank intentionally]

Table of Contents

Table of Contents	4
ROCm Installation Updates	5
List of Supported Operating Systems	5
Complete Installation of AMD ROCm v4.3.1 Recommended	5
ROCm Multi-Version Installation Update	6
AMD ROCm V4.3.1 Documentation Updates	7
AMD ROCm Installation Guide	7
AMD ROCm General Documentation Links	7
What's New in This Release	8
Support for RHEL v8.4	8
Support for SLES v15 Service Pack 3	8
Pass Manager Update	8
Known Issues in This Release	9
General UserSpace and Application Freeze on MI25	9
hipRTC - File Not Found Error	9
Hardware and Software Support	10
Hardware Support	10
Supported Graphics Processing Units	10
Supported CPUs	
Not supported or limited support under ROCm	
ROCm Support in Upstream Linux Kernels	15

ROCm Installation Updates

This document describes the features, fixed issues, and information about downloading and installing the AMD ROCmTM software.

It also covers known issues and deprecations in this release.

LIST OF SUPPORTED OPERATING SYSTEMS

The AMD ROCm platform supports the following operating systems:

OS	Kernel
SLES15 SP3	5.3.18-24.49
RHEL 7.9	3.10.0-1160.6.1.el7
CentOS 7.9	3.10.0-1127
RHEL 8.4	4.18.0-193.1.1.el8
CentOS 8.3	4.18.0-193.el8
Ubuntu 18.04.5	5.4.0-71-generic
Ubuntu 20.04.2	5.8.0-48-generic

COMPLETE INSTALLATION OF AMD ROCM V4.3.1 RECOMMENDED

Complete uninstallation of previous ROCm versions is required before installing a new version of ROCm. An upgrade from earlier releases to AMD ROCm v4.3.1 is not supported. For more information, refer to the <u>AMD ROCm Installation Guide</u>.

Note: AMD ROCm release v3.3 or prior releases are not fully compatible with AMD ROCm v3.5 and higher versions. You must perform a fresh ROCm installation if you want to upgrade from AMD ROCm v3.3 or older to 3.5 or higher versions and vice-versa.

Note: *render group* is required only for Ubuntu v20.04. For all other ROCm supported operating systems, continue to use *video group*.

- For ROCm v3.5 and releases thereafter, the clinfo path is changed to /opt/rocm/opencl/bin/clinfo.
- For ROCm v3.3 and older releases, the clinfo path remains /opt/rocm/opencl/bin/x86 64/clinfo.

ROCM MULTI-VERSION INSTALLATION UPDATE

With the AMD ROCm v4.3.1 release, the following ROCm multi-version installation changes apply:

The meta packages *rocm-dkms*<*version*> are now deprecated for multi-version ROCm installs. For example, *rocm-dkms3.7.0*, *rocm-dkms3.8.0*.

- Multi-version installation of ROCm should be performed by installing *rocm-dev*<*version*> using each of the desired ROCm versions. For example, *rocm-dev3.7.0*, *rocm-dev3.8.0*, *rocm-dev3.9.0*.
- Install the rock-dkms loadable kernel modules using a single *rock-dkms* package.
- ROCm v4.3.1 and above will not set any *ldconfig* entries for ROCm libraries for multi-version installation. Users must set *LD LIBRARY PATH* to load the ROCm library version of choice.

NOTE: The single version installation of the ROCm stack remains the same. The *rocm-dkms* package can be used for single version installs and is not deprecated at this time.

AMD ROCm V4.3.1 Documentation Updates

AMD ROCM INSTALLATION GUIDE

The AMD ROCm Installation Guide in this release includes the following updates:

- Supported Environments
- Installation Instructions

AMD ROCM GENERAL DOCUMENTATION LINKS

- For AMD ROCm documentation, see <u>https://rocmdocs.amd.com/en/latest/</u>
- For installation instructions on supported platforms, see https://rocmdocs.amd.com/en/latest/Installation Guide/Installation-Guide.html
- For AMD ROCm binary structure, see https://rocmdocs.amd.com/en/latest/Installation_Guide/Software-Stack-for-AMD-GPU.html
- For AMD ROCm release history, see https://rocmdocs.amd.com/en/latest/Current_Release_Notes/ROCm-Version-History.html

What's New in This Release

The ROCm v4.3.1 release consists of the following enhancements:

SUPPORT FOR RHEL V8.4

This release extends support for RHEL v8.4.

SUPPORT FOR SLES V15 SERVICE PACK 3

This release extends support for SLES v15 SP3.

PASS MANAGER UPDATE

In the AMD ROCm 4.3.1 release, the ROCm compiler uses the legacy pass manager, by default, to provide a better performance experience with some workloads.

Previously, in ROCm v4.3, the default choice for the ROCm compiler was the new pass manager.

For more information about legacy and new pass managers, see http://llvm.org.

Known Issues in This Release

GENERAL USERSPACE AND APPLICATION FREEZE ON MI25

For some workloads on MI25, general user space and application freeze are observed, and the GPU resets intermittently. Note, the freeze may take hours to reproduce.

This issue is under active investigation, and no workarounds are available currently.

HIPRTC - FILE NOT FOUND ERROR

hipRTC may fail, and users may encounter the following error:

```
<built-in>:1:10: fatal error: '__clang_hip_runtime_wrapper.h' file not found
#include " clang hip runtime wrapper.h"
```

Suggested Workarounds

- Set *LLVM_PATH* in the environment to <*path to ROCm llvm>/llvm*.

 Note, if ROCm is installed at the default location, then *LLVM PATH* must be set to /*opt/rocm/llvm*.
- Add "-I < path to ROCm>/llvm/lib/clang/13.0.0/include/" to compiler options in the call to hiprtcCompileProgram ().

Note, this workaround requires the following changes in the code:

```
// set NUM_OPTIONS to one more than the number of options that was previously
required
const char* options[NUM_OPTIONS];
// fill other options[] here
std::string sarg = "-I/opt/rocm/llvm/lib/clang/13.0.0/include/";
options[NUM_OPTIONS - 1] = sarg.c_str();
hiprtcResult compileResult{hiprtcCompileProgram(prog, NUM_OPTIONS, options)};"
```

Hardware and Software Support

HARDWARE SUPPORT

ROCm is focused on using AMD GPUs to accelerate computational tasks such as machine learning, engineering workloads, and scientific computing. To focus our development efforts on these domains of interest, ROCm supports the following targeted set of hardware configurations.

Supported Graphics Processing Units

As the AMD ROCm platform has a focus on specific computational domains, AMD offers official support for a selection of GPUs that are designed to offer good performance and price in these domains.

Note: The integrated GPUs of Ryzen are not officially supported targets for ROCm.

ROCm officially supports AMD GPUs that use the following chips:

- GFX9 GPUs
 - o "Vega 10" chips, such as on the AMD Radeon RX Vega 64 and Radeon Instinct MI25
 - "Vega 7nm" chips, such as on the Radeon Instinct MI50, Radeon Instinct MI60, AMD Radeon VII, Radeon Pro VII
- CDNA GPUs
 - o MI100 chips such as on the AMD InstinctTM MI100

ROCm is a collection of software ranging from drivers and runtimes to libraries and developer tools. Some of this software may work with more GPUs than the "officially supported" list above, though AMD does not make any official claims of support for these devices on the ROCm software platform.

The following list of GPUs is enabled in the ROCm software. However, full support is not guaranteed:

- GFX8 GPUs
 - o "Polaris 11" chips, such as on the AMD Radeon RX 570 and Radeon Pro WX 4100
 - o "Polaris 12" chips, such as on the AMD Radeon RX 550 and Radeon RX 540
- •
- GFX7 GPUs
 - o "Hawaii" chips, such as the AMD Radeon R9 390X and FirePro W9100

As described in the next section, GFX8 GPUs require PCI Express 3.0 (PCIe 3.0) with support for PCIe atomics. This requires both CPU and motherboard support. GFX9 GPUs require PCIe 3.0 with support for PCIe atomics by default, but they can operate in most cases without this capability.

The integrated GPUs in AMD APUs are not officially supported targets for ROCm. As described <u>below</u>, "Carrizo", "Bristol Ridge", and "Raven Ridge" APUs are enabled in AMD upstream drivers and the ROCm

OpenCL runtime. However, they are not enabled in the HIP runtime, and may not work due to motherboard or OEM hardware limitations. Note, they are not yet officially supported targets for ROCm.

GFX8 GPUS

Note: The GPUs require a host CPU and platform with PCIe 3.0 with support for PCIe atomics.

	GFX8 GPUs		
Fiji (AMD)	Polaris 10 (AMD)	Polaris 11 (AMD)	Polaris 12 (Lexa) (AMD)
 Radeon R9 Fury Radeon R9 Nano Radeon R9 Fury X Radeon Pro Duo (Fiji) FirePro S9300 X2 Radeon Instinct M18 	 Radeon RX 470 Radeon RX 480 Radeon RX 570 Radeon RX 580 Radeon Pro Duo (Polaris) Radeon Pro WX 5100 Radeon Pro WX 7100 Radeon Instinct MI6 	 Radeon RX 460 Radeon RX 560 Radeon Pro WX 4100 	 Radeon RX 540 Radeon RX 550 Radeon Pro WX 2100 Radeon Pro WX 3100

GFX9 GPUS

ROCm offers support for two chips from AMD's most recent "gfx9" generation of GPUs.

GFX9 GPUs		
Vega 10 (AMD)	Vega 7nm (AMD)	
 Radeon RX Vega 56 Radeon RX Vega 64 Radeon Vega Frontier Edition Radeon Pro WX 8200 	 Radeon VII Radeon Instinct MI50 Radeon Instinct MI60 	

- Radeon Pro WX 9100
- Radeon Pro V340
- Radeon Pro V340 MxGPU
- Radeon Instinct MI25

Note: ROCm does not support Radeon Pro SSG.

•

SUPPORTED CPUS

As described above, GFX8 GPUs require PCIe 3.0 with PCIe atomics to run ROCm. In particular, the CPU and every active PCIe point between the CPU and GPU require support for PCIe 3.0 and PCIe atomics. The CPU root must indicate PCIe AtomicOp Completion capabilities and any intermediate switch must indicate PCIe AtomicOp Routing capabilities.

The current CPUs which support PCIe Gen3 + PCIe Atomics are:

- AMD Ryzen CPUs
- CPUs in AMD Ryzen APUs
- AMD Ryzen Threadripper CPUs
- AMD EPYC CPUs
- Intel Xeon E7 v3 or newer CPUs
- Intel Xeon E5 v3 or newer CPUs
- Intel Xeon E3 v3 or newer CPUs
- Intel Core i7 v4, Core i5 v4, Core i3 v4 or newer CPUs (i.e. Haswell family or newer)
- Some Ivy Bridge-E systems

Beginning with ROCm 1.8, GFX9 GPUs (such as Vega 10) no longer require PCIe atomics. We have similarly made more options available for many PCIe lanes. GFX9 GPUs can now be run on CPUs without PCIe atomics and on older PCIe generations, such as PCIe 2.0. This is not supported on GPUs below GFX9, e.g. GFX8 cards in the Fiji and Polaris families.

If you are using any PCIe switches in your system, please note that PCIe Atomics are only supported on some switches, such as Broadcom PLX. When you install your GPUs, make sure you install them in a PCIe 3.0 x16, x8, x4, or x1 slot attached either directly to the CPU's Root I/O controller or via a PCIe switch directly attached to the CPU's Root I/O controller.

In our experience, many issues stem from trying to use consumer motherboards which provide physical x16 connectors that are electrically connected as e.g. PCIe 2.0 x4, PCIe slots connected via the Southbridge PCIe I/O controller, or PCIe slots connected through a PCIe switch that does not support PCIe atomics.

If you attempt to run ROCm on a system without proper PCIe atomic support, you may see an error in the kernel log (dmesg):

kfd: skipped device 1002:7300, PCI rejects atomics

Experimental support for our Hawaii (GFX7) GPUs (Radeon R9 290, R9 390, FirePro W9100, S9150, S9170) does not require or take advantage of PCIe Atomics. However, AMD recommends that you use a CPU from the list provided above for compatibility purposes.

NOT SUPPORTED OR LIMITED SUPPORT UNDER ROCM

LIMITED SUPPORT

- ROCm 4.x should support PCIe 2.0 enabled CPUs such as the AMD Opteron, Phenom,
 Phenom II, Athlon, Athlon X2, Athlon II and older Intel Xeon and Intel Core Architecture
 and Pentium CPUs. However, we have done very limited testing on these configurations,
 since our test farm has been catering to CPUs listed above. This is where we need
 community support.
- Please report these issues.
 - Thunderbolt 1, 2, and 3 enabled breakout boxes should now be able to work with ROCm. Thunderbolt 1 and 2 are PCIe 2.0 based, and thus are only supported with GPUs that do not require PCIe 3.0 atomics (e.g. Vega 10). However, we have done no testing on this configuration and would need community support due to limited access to this type of equipment.
 - AMD "Carrizo" and "Bristol Ridge" APUs are enabled to run OpenCL, but do not yet support HIP or our libraries built on top of these compilers and runtimes.
 - As of ROCm 2.1, "Carrizo" and "Bristol Ridge" require the use of upstream kernel drivers.
 - In addition, various "Carrizo" and "Bristol Ridge" platforms may not work due to OEM and ODM choices when it comes to key configuration parameters such as the inclusion of the required CRAT tables and IOMMU configuration parameters in the system BIOS.
 - Before purchasing such a system for ROCm, please verify that the BIOS provides an option for enabling IOMMUv2 and that the system BIOS properly exposes the correct CRAT table. Inquire with your vendor about the latter.
 - AMD "Raven Ridge" APUs are enabled to run OpenCL, but do not yet support HIP or our libraries built on top of these compilers and runtimes.
 - o As of ROCm 2.1, "Raven Ridge" requires the use of upstream kernel drivers.
 - ODM choices when it comes to key configuration parameters such as the inclusion

- of the required CRAT tables and IOMMU configuration parameters in the system BIOS.
- o Before purchasing such a system for ROCm, please verify that the BIOS provides an option for enabling IOMMUv2 and that the system BIOS properly exposes the correct CRAT table. Inquire with your vendor about the latter.

NOT SUPPORTED

- "Tonga", "Iceland", "Vega M", and "Vega 12" GPUs are not supported.
- AMD does not support GFX8-class GPUs (Fiji, Polaris, etc.) on CPUs that do not have PCIe3.0 with PCIe atomics.
 - o AMD Carrizo and Kaveri APUs as hosts for such GPUs are not supported
 - o Thunderbolt 1 and 2 enabled GPUs are not supported by GFX8 GPUs on ROCm. Thunderbolt 1 & 2 are based on PCIe 2.0.

In the default ROCm configuration, GFX8 and GFX9 GPUs require PCI Express 3.0 with PCIe atomics. The ROCm platform leverages these advanced capabilities to allow features such as user-level submission of work from the host to the GPU. This includes PCIe atomic Fetch and Add, Compare and Swap, Unconditional Swap, and AtomicOp Completion.

Current CPUs which support PCIe 3.0 + PCIe Atomics:

AMD	INTEL
Ryzen CPUs (Family 17h Model 01h-0Fh) Ryzen 3 1300X Ryzen 3 2300X Ryzen 5 1600X Ryzen 5 2600X Ryzen 7 1800X Ryzen 7 2700X	Intel Core i3, i5, and i7 CPUs from Haswell and beyond. This includes: • Haswell CPUs such as the Core i7 4790K • Broadwell CPUs such as the Core i7 5775C • Skylake CPUs such as the Core i7 6700K • Kaby Lake CPUs such as the Core i7 7740X • Coffee Lake CPUs such as the Core i7 8700K • Xeon CPUs from "v3" and newer • Some models of "Ivy Bridge-E" processors
Ryzen APUs (Family 17h Model 10h-1Fh – previously code-named Raven Ridge) such as:	

Athlon 200GERyzen 5 2400G	
Note: The integrated GPU in these devices is not guaranteed to work with ROCm.	
Ryzen Threadripper Workstation CPUs (Family 17h Model 01h-0Fh) such as: • Ryzen Threadripper 1950X • Ryzen Threadripper 2990WX	
EPYC Server CPUs (Family 17h Model 01h-0Fh) such as:	
Epyc 7551PEpyc 7601	

ROCM SUPPORT IN UPSTREAM LINUX KERNELS

As of ROCm 1.9.0, the ROCm user-level software is compatible with the AMD drivers in certain upstream Linux kernels.

As such, users have the option of either using the ROCK kernel driver that are part of AMD's ROCm repositories or using the upstream driver and only installing ROCm user-level utilities from AMD's ROCm repositories.

These releases of the upstream Linux kernel support the following GPUs in ROCm:

- 4.17: Fiji, Polaris 10, Polaris 11
- 4.18: Fiji, Polaris 10, Polaris 11, Vega10
- 4.20: Fiji, Polaris 10, Polaris 11, Vega10, Vega 7nm

The upstream driver may be useful for running ROCm software on systems that are not compatible with the kernel driver available in AMD's repositories.

For users that have the option of using either AMD's or the upstreamed driver, there are various tradeoffs to take into consideration:

		Using AMD's rock-dkms package	Using the upstream kernel driver
--	--	----------------------------------	----------------------------------

Pros	More GPU features and are enabled earlier	Includes the latest Linux kernel features
	Tested by AMD on supported distributions	May work on other distributions and with custom kernels
	Supported GPUs enabled regardless of kernel version	
	Includes the latest GPU firmware	
Cons	May not work on all Linux distributions or versions	Features and hardware support varies depending on the kernel version
	Not currently supported on kernels newer than 5.4	Limits GPU's usage of system memory to 3/8 of system memory (before 5.6). For 5.6 and beyond, both DKMS and upstream kernels allow the use of 15/16 of system memory.
		IPC and RDMA capabilities are not yet enabled
		Not tested by AMD to the same level as rock-dkms package
		Does not include the most up-to-date firmware