UNTESTED +3V3 TRADFRI RESETN PF3 PF2 PF1 PF0 PC11 PC10 PB14 PB15 RESETn PA0 PA1 PB12 PB13 GND VCC SWO SWDIO SWCLK 7 8 9 10 Right GND GND GND +3V3 RESETn SWDIO SWCLK SWO + C1 RESET SW1 T SWDIO SWCLK SWO GND S (ND R1 RESETn RESETn JTAG GND GND GND GND GND ARM-JTAG