

NGOD Engineering Change Request

Engineering Change Request (ECR) title:	ECR ID (assigned by PM):	
"R2 change for Start Over"		
Name of originator:	Date raised:	
James Baratz	11/30/07	
Engineering Change Request Information		
Engineering Change Request detailed description:		
This is the change to send data to the SS for trick mode enforcement.		
Impact on:		
•		
Engineering Change Request Revision Change History		
List of Specification(s) affected:	Type of Change/Severity (Tech/Edit/Both):	
-	- Non-critical: Formatting (text) change	
	- Minor: Technical change	
	- Major: Technical change	

- To be filled out upon CCB decision

Changes to be implemented by the NGOD Technical Team:

Primary Assignee:	Secondary Assignee / Vendor:	
Action	Action by	Date Modified
Comments:		Status:

Change to General RTSP Usage Spec

Section 9.2 Playlist item

Replace

a=X-playlist-item: cyrovider-id> <asset-id>[<range>]

with

a=X-playlist-item: cyrovider-id> <asset-id>[<range>][tricks/[F][R][P]]

Add new Section or combine with 9.2 and make current 9.2.1

9.X X-trickcontrol



NGOD Engineering Change Request

a=X-trickControl: <uri>

Change to SRM R2 Spec

Use the volume name "library" for asset that is located in the remote regional library. In this case, the Streaming Server is required to use ALQ to query ALS for asset location If the asset is not in its local cache.

Change to SRM_S1C1_RTSP

Appendix I Section I-1 Table 2

Add entry

498 TrickModeNotAllowed.

Changes to SRM_S1C1_DSMCC

Add to section 6 new section

6.4 Error Codes.

There is an addition LSC error code used by NGOD to signal the client that a trick mode request such as FF in a start over situation is rejected according to business rules. The following should be considered as a logical extension to the table in section 8.6 Status Codes in the LSC specification.

"LSC_NOT_PERMITTED 0x1b Stream Control function disallowed by business rules."