Gear

Summary

To create a gear, you should input the number of the teeth, pressure angle, diameter pitch, the thickness.

If you choose the curve option, it will create gear profile curves.

If you choose the solid option, it will create a solid gear.

User Interface

The user interface is created using a BlockForm:



