# Draw Text

Summary

Converts a TrueType font string into curves, and then extrudes them.

To finish the process, you should select font, input string, specify position, and input thickness.

User Interface

Choose the windows font to be used


Input the string to be extruded

Specify position where extrusion will be located

The thickness (distance) of the extrusion

Input the thickness (distance) of the extrusion

Sample Output