

MR.142 / MR.146-MR.154 High-Load Axial-Support Bearings

Complete geometry and ratings for high-load combined bearings with hardened axial support.

Geometry

Model	Support	d	D	C	H	H1	H2	D1	C1	d1	S	Angle	r	R	R1	D2	d2	H3
MR.146	MR.146G2	30	62	20	43	33	10	50	16	42	5.5	20	3	500	500	40	25	22
MR.147	MR.146G2	35	70.1	23	48	40	8	57	16	48	6.5	20	4	500	500	40	25	22
MR.148	MR.148G2	40	77.7	23	50.5	39.5	11	61	21	54	7	20	4	700	700	52	33	28
MR.149	MR.148G2	40	78.3	23	45	34	11	61	21	54	7	20	4	850	700	52	33	28
MR.150	MR.148G2	45	88.9	30	61	48	13	69.5	21	59	7	20	3	850	700	52	33	28
MR.151	MR.151G2	50	101.9	28	50.5	37.5	13	77	21	67	7	20	3	850	700	52	33	28
MR.142 / 4.0784	MR.142G2	60	107.7	31	69	55	14	82	33	71	8	20	4	1000	700	74	48	38
MR.152 / 4.078	MR.142G2	55	108.55	31	58.5	44.5	14	82	33	71	8	20	4	1000	700	74	48	38
MR.153	MR.142G2	60	123	37	75.8	59.5	16.3	92	33	78	8	20	4	1000	1000	74	48	38
MR.154	MR.154G2	60	149	43	89	69	20	116	50	103	15	15	4	1000	1000	105	72	>55

Load ratings, speed and mass

Model	Cr kN	C0r kN	Ca kN	C0a kN	Speed rpm	Mass kg
MR.146	39	65	10	14	900	0.60
MR.147	56	93	10	14	900	0.90
MR.148	58	101.5	14	22	800	1.05
MR.149	58	101.5	14	22	800	0.95
MR.150	84	133	14	22	700	1.70
MR.151	91	153	18	22	700	1.85
MR.142 / 4.0784	94	162	39	57	650	2.40
MR.152 / 4.078	94	162	39	57	650	2.80
MR.153	132	242	39	57	500	4.10
MR.154	179	353	83	131	400	6.80

Verification notes

- Adapter washers: 0.3, 0.5 and 1.0 mm.

- MR.142 cross-references 4.0784; MR.152 cross-references 4.078.

Confirm the current controlled drawing, suffix, mounting geometry, load case, lubrication, temperature and inspection scope before ordering.