
DISCHARGING PLAN

Date: 04-09-2022 10:12:00


Port: BDCGP



VOY NO: SC234A

DISCHARGING PLAN(OPERATOR)


Port : BDCGP Date : 04-09-2022 10:12:00



DISCHARGING PLAN(SPECIAL CONTAINER)


Date: 04-09-2022 10:12:00

Port: BDCGP



DISCHARGING PLAN(DELIVERY)


Port : BDCGP



DISCHARGING PLAN(IMDG)

Port: BDCGP

Date: 04-09-2022 10:12:00



DISCHARGING PLAN(LASHING SUMMARY)


Date: 04-09-2022 10:12:00

Port: BDCGP

VOY NO: SC234A **BAY 17 BAY 13 BAY 05 BAY 21 BAY 09 BAY 01** 06 04 02 00 01 03 05 07 B2 $82 \times |\times| \times |$ $\overline{\times}|\overline{\times}|\overline{\times}|\overline{\times}|\times$ $\times |\times| \times |\times| \times |\times|$ $\times |\times| \times |\times| \times |\times|$ B2 × × × B2 **BAY 19(18)** BAY 07(06) BAY 23(22) **BAY 15(14)** BAY 11(10) BAY 03(02) B2 B2 B2 B2 B2 B2 B2 B2 B2 B2. B2 82 B2 82 B2 00 01 **BAY 29 BAY 25** $\times |\times| \times |\times| \overline{\times}|$ B2 BAY 27(26) **BAY 31(30)** B2 TOTAL OTY

DISCHARGING PLAN(SPECIAL CARGO)


Port : BDCGP



DISCHARGING PLAN(WEIGHT GROUP)

Port: BDCGP


Date: 04-09-2022 10:12:00



DISCHARGING PLAN(SHIFTING)

Port: BDCGP

Date: 04-09-2022 10:12:00




VOY NO: SC234A

DISCHARGING PLAN(HANDLING INSTRUCTION)

Date: 04-09-2022 10:12:00

Port: BDCGP



VVD : OEL COLOMBO VOY NO : SC234A

DG Cargo Detail Information

Port : BDCGP Date : 04-09-2022 10:12:00

Cell Position	Container No	POL	POD	TOD	OPR	DEST	FPOD	ISO TpSz	TpSz	WGT	Class	UNNO	PG	F.P	Sub.Risk	NET.W
020210	MSDU4434509	LKCMB	BDCGP	BDCGPCC	MSC	UNSET	BDCGP	4310	40DV	22.6	8	3265	3			3600
020010	CAIU4053340	LKCMB	BDCGP	BDCGPCC	MSC	UNSET	BDCGP	42G0	40DV	29.7	8	1760	2	69C		6000
020110	MSDU4088068	LKCMB	BDCGP	BDCGPCC	MSC	UNSET	BDCGP	4310	40DV	29.6	8	1760	3			12000
030410	MEDU3456661	LKCMB	BDCGP	BDCGPCC	MSC	UNSET	BDCGP	2210	20DV	8.2	3	1263	3	+51C		90
030310	FCIU3266695	LKCMB	BDCGP	BDCGPCC	MSC	UNSET	BDCGP	22G0	20DV	9.0	61	1690	3			6000
130282	TCLU6975481	LKCMB	BDCGP	BDCGPCC	MSC	UNSET	BDCGP	2210	20DV	22.6	41	2213	3			20000
130284	MEDU6205850	LKCMB	BDCGP	BDCGPCC	MSC	UNSET	BDCGP	2210	20DV	10.9	9	3082	3			1800
130082	MSDU2929392	LKCMB	BDCGP	BDCGPCC	MSC	UNSET	BDCGP	2210	20DV	22.9	8	2801	3			20000
130084	MSDU1995091	LKCMB	BDCGP	BDCGPCC	MSC	UNSET	BDCGP	2210	20DV	22.7	41	2213	3			20000
130182	FTAU1354204	LKCMB	BDCGP	BDCGPCC	MSC	UNSET	BDCGP	2210	20DV	22.6	41	2213	3			20000
130184	MSDU2527958	LKCMB	BDCGP	BDCGPCC	MSC	UNSET	BDCGP	2210	20DV	22.7	41	2213	3			20000
130382	MEDU5294641	LKCMB	BDCGP	BDCGPCC	MSC	UNSET	BDCGP	2210	20DV	22.7	41	2213	3			20000
140682	TRHU7206224	LKCMB	BDCGP	BDCGPCC	MSC	UNSET	BDCGP	4510	40HC	25.6	3	1263	3	+25C		20000
140482	MEDU9485224	LKCMB	BDCGP	BDCGPCC	MSC	UNSET	BDCGP	4510	40HC	26.2	9	3082	3			3000
140484	MSMU6373498	LKCMB	BDCGP	BDCGPCC	MSC	UNSET	BDCGP	4510	40HC	25.5	3	1263	3	+25C		20000
140582	MSMU6369158	LKCMB	BDCGP	BDCGPCC	MSC	UNSET	BDCGP	4510	40HC	28.8	9	3077	3			650
140584	MSMU6296874	LKCMB	BDCGP	BDCGPCC	MSC	UNSET	BDCGP	4510	40HC	19.7	8	3264	2			400
150282	MSDU1145267	LKCMB	BDCGP	BDCGPCC	MSC	UNSET	BDCGP	2210	20DV	22.6	41	2213	3			20000
150284	MEDU3262584	LKCMB	BDCGP	BDCGPCC	MSC	UNSET	BDCGP	2210	20DV	11.3	8	2491	3			8400
150082	CAIU2899746	LKCMB	BDCGP	BDCGPCC	MSC	UNSET	BDCGP	2210	20DV	22.7	41	2213	3			20000
150084	MEDU6183766	LKCMB	BDCGP	BDCGPCC	MSC	UNSET	BDCGP	2210	20DV	22.7	41	2213	3			20000
150182	MEDU5943817	LKCMB	BDCGP	BDCGPCC	MSC	UNSET	BDCGP	2210	20DV	22.7	41	2213	3			20000
150184	TGHU3070333	LKCMB	BDCGP	BDCGPCC	MSC	UNSET	BDCGP	2210	20DV	18.6	8	2801	3			10000
150382	MSDU1252183	LKCMB	BDCGP	BDCGPCC	MSC	UNSET	BDCGP	2210	20DV	22.7	41	2213	3			20000

OOG Detail Information VVD: OEL COLOMBO VOY NO: SC234A Date: 04-09-2022 10:12:00

Cell Position	Container No	POL	TOL	POD	TOD	OPR	DEST	FPOD	ISO TpSz	TpSz	WGT	Over Slot(H/P/S/F/A)	Over Size(H/P/S/F/A)
100186	TCLU7009970	LKCMB	LKJC1	BDCGP	BDCGPCC	MSC	UNSET	BDCGP	4351	40OT	11.2	1/0/0/0/0	50/0/0/0/0

For 2M services the cost of restows are to be split between MSC and Maersk in proportion to the moves on the vessel at your terminal. For example on a vessel with 600 Moves for MSC (and the subsidiaries) and 400 moves for Maersk (and their subsidiaries) where there are 10 restows then 6 will be for the account of MSC and 4 for the account of Maersk irrespective of the vessel or container operator. Where the proportion of restows is not a 'full number', the restows should be rounded up or down to the nearest full number always ensuring the total is correct. On occasions where there are restows arising out of a Change of Destination all of those restows are for the account of that operator with the balance of restows to be split in the way described

Port: BDCGP

User: okravchenk

VVD : OEL COLOMBO VOY NO : SC234A

Long Hatch Arrangement

Port: BDCGP Date: 04-09-2022 10:12:00

HT0	HT1	HT2	HT3	HT4	HT5	HT6	HT7	Total	Handling				
8	7	6	5	4	3	2	1	Summary	Hatch				
30	26	22	18	14	10	06	02		Bay No.				
0	2	2	2	2	2	1	1	12	Open Hatch No.				
0	0	0	0	0	0	0	0	0	Shifting(H)				
0	0	0	0	0	0	0	0	0	Shifting(D)				
0	33	49	49	49	47	30	21	278	Discharging(H)				
18	18	18	17	35	23	17	17	163	Discharging(D)				
0	0	0	0	0	0	0	0	0	Loading(H)				
0	0	0	0	0	0	0	0	0	Loading(D)				
0	33	49	49	49	47	30	21	278	Total(H)				
18	18	18	17	35	23	17	17	163	Total(D)				
18	51	67	66	84	70	47	38	441	Grand Total				

	Crane 1	Crane 2	Crane 3	Crane 4	Crane 5	Crane 6	Crane 7	Crane 8	Crane 9
Moves	0	0	0	0	0	0		0	

User: okravchenk