

Input Ports

Input Ports 1, 2, 3, and 4 are used to connect sensors to the EV3 Brick.



Output Ports

Output Ports A, B, C, and D are used to connect motors to the EV3 Brick.





LARGE MOTOR

PORTS

Input Ports

Input Ports 1, 2, 3, and 4 are used to connect sensors to the EV3 Brick.



Output Ports

Output Ports A, B, C, and D are used to connect motors to the EV3 Brick.

