



Note: RWY23 End displaced 150m inwards.



| TAKE-OFF MINIMA(WITH RELIABLE ALTN)(m) |                  |                  |                  |                  | LIGHTS                            |                                   |
|--|------------------|------------------|------------------|------------------|-----------------------------------|-----------------------------------|
| ACFT Type                              | RWY05            |                  | RWY23            |                  | RWY05                             | RWY23                             |
|  | REDL             | NIL(Day only)    | REDL             | NIL(Day only)    |                                   |                                   |
| 2 TURB ENG B C D                       | RVR400<br>VIS800 | RVR500<br>VIS800 | RVR400<br>VIS800 | RVR500<br>VIS800 | PALS CAT I<br>SFL<br>PAPI<br>REDL | PALS CAT I<br>SFL<br>PAPI<br>REDL |
| Other 1&2 ENG                          |                  |                  |                  |                  | RCLL                              | RCLL                              |

Note:

Changes: Taxi B8 withdrawn, APN.