

ENGINEER CHANGE ORDER (ECO) ANALYSIS FORM

	*
Manufacturer:	Election Systems & Software (ES&S)
System:	DS200, Hardware 1.3.10.0
ECO Number:	983
ECO Description:	Modified DS 200 housing to add texture free areas across exterior housing seams for security seals

Overview:

Texture free areas were added to the DS200 across exterior housing seams for security seals.

Systems Affected:

EVS 5000, EVS 5010, EVS 5200, EVS 5203, EVS 5204, EVS 5210, EVS 5211, EVS 5220, EVS 5230, EVS 5240, EVS 5400, EVS 5410, EVS 6000

Federal: EVS 5000, EVS 5010, EVS 5200, EVS 5203, EVS 5204, EVS 5210, EVS 5211, EVS 5220, EVS 5230, EVS 5240, EVS 5400, EVS 5410, EVS 6000

State: FL EVS 4500 Ver. 4, FL EVS 4520, FL EVS 4530 Ver. 1, EVS 5002, EVS 5003 Rev. 1, EVS 5004, EVS 5100, EVS 5110, EVS 5201, EVS 5202, EVS 5300, EVS 5303, EVS 5310, EVS 5320, EVS 5321, EVS 5330, EVS 5340, EVS 5501, EVS 5502, EVS 5601, EVS 5602, EVS 6010, IL EVS 5300

Supporting Documentation:

ECO-983 Signed.pdf

Engineering Recommendation:

Technical documentation review performed to approve change. Per ES&S, DS 200 housings can be retrofit in the field as required. Pro V&V determined that the modification will not adversely affect any system functions. No form changes should affect part fit. No additional testing required.

Engineering Analysis: De Minimis	
Reviewer:	Approver:
Wendy Owens Printed Name	Michael L. Walker Printed Name
Wordey Queus Signature	Muleul & Walts
	/2/12/18 Date

Engineering Change Order

ECO# 983	Requested by	Kevin Liesner	Date: 7/9/2018
Model DS200	Product Line Engineer	Derek Caviness	Rev: A
Description of Change: In layman's tems, itemize and describe what the change is. For example, "Add shim beneath the end of the USB mounting bracket."	<u>-</u>	Add texture free areas across exterior housing seams for security seals.	y seals.
Reason For Change: In layman's terms, itemize and describe the requirement that is not being met. For example, "Shim increases the engagement of the back-up USB stick."	1. EC	Additional security is becoming a market expectation, beginning with California O Category: Modify an Existing Part or Assembly	with California.
ECO Notes Related ECOs, Temporary Deviations, Field Retrofft, etc.	Related ECOS: N/A Temporary Deviations (in-process Production): N/A Field Retrofit: Housings can be retrofit in the field as	Related ECOS: N/A Temporary Deviations (in-process Production): N/A Field Retrofft: Housings can be retrofit in the field as required	
	4. Mod to the Mfg Prep Prcs or QC Checklist required? 5. Internal Retrofit (Cert & Training Equipment): HW Er		No List: Update Cert, QA and Training units
Certification Impact Impact on hardware configuration, list of tests performed, recommended federal cert	4	.3.10.0 Material will be tested for form/fit/functional affect part fit.	Hardware Configuration: 1.3.10.0 Internal Testing Performed: Material will be tested for form/fit/function when samples arrive week 2, October 2018. No form changes should affect part fit.
strategy, approach to state cert (N.E.W.S).	3. Submit to VSTL: 4. Affected Systems: EVS500 6000	<u>l' No</u> 00, EV5010, EVS5200, 5203, 5204, 52	Submit to VSTL: Yes No Affected Systems: EVS5000, EVS5200, 5203, 5204, 5210, 5211, 5220, 5230, 5240, 5400, 5410, 6000
	EVS 5230, EVS 5240, EVS 5240, EVS State: FL EVS 4500 Ve	VS 5010, EVS 5200, EVS 5203, EVS £ 5400, EVS 5410, EVS 6000 r 4, FL EVS 4520, FL EVS 4530 Ver 1, EVS	EVS 5230, EVS 5000, EVS 5010, EVS 5200, EVS 5203, EVS 5204, EVS 5210, EVS 5211, EVS 5220, EVS 5230, EVS 5240, EVS 5400, EVS 5410, EVS 6000 State: FL EVS 4500 Ver 4, FL EVS 4520, FL EVS 4530 Ver 1, EVS 5002, EVS 5003 Rev 1, EVS 5004 EVS 5400 EVS 5440 EVS 5440 EVS 5440 EVS 5400 EVS 5440 EVS
	5. <u>Federal Cert Strategy:</u> Click here to enter text	5054, EVS 5164, EVS 5114, EVS 5261, EVS 5262, EVS 55601, EVS 5502, EVS 6010, IL EVS 5300 5321, EVS 5330, EVS 5340, EVS 5501, EVS 5502, EVS 5601, EVS 5602, EVS 6010, IL EVS 5300 <u>Federal Cert Strategy.</u> Click here to enter text.	vs 5502, Evs 6010, Evs 5520, Evs VS 5602, EVS 6010, IL EVS 5300
	6. State Cert Strategy: Click here to enter text. Test to: V1.0 VVSG Standards	here to enter text. Standards	

6-10-10 MATERIALS MANAGMENT: -DATE: -

MANUFACTURING: -DATE: - 10/10/

QUALITY ASSURANCE:

10[10|20/18 DATE: -

1 of 3

ECO-983



Engineering Change Order

Part Specific Changes:

PLM Documentation & Pivot Production

ES&S Bin Number & Omaha Inventory Include order qty and re-buy levels for new parts. Notify order entry as applicable.

67500 - DS200(i) Digital Precinct Scanner Paper Tabulator

×1.3

2		- 6	/B	
REVISED PARTS	Include the part number, title, and brief description of the	change. In addition, provide direction on what should be done with existing maferial.	what locations are affected by this change, and what is	the new part revision

Add texture free areas to the plastic parts (config change FNs 7, 8, 10, 14, 15, and 45), Break-in change 098-00041- ASSY Final DS200 Hardware Revision 1.3: as part of production build 1.3.10, Rev goes to P

097-00272 - ASSY MECH DS200 Display LCD/TS: Add texture free areas (config change FNs 1 & 3), Balance change w/ bottom housing (59-00353), Rev goes to F.

01-059-00026 - HSG DS200 LCD BEZEL PC/ABS: Add texture free areas, Balance change w/ bottom housing (59-00353), Rev goes to D.

01-059-00028 - CVR DS200 LCD PC/ABS: Add texture free areas, Balance change w/ bottom housing (59-00353), Rev goes to F. 01-059-00029 - CVR DS200 FRONT PC/ABS: Add texture free areas, Balance change w/ bottom housing (59-00353), Rev goes to G. 11-059-00030 - CVR DS200 SWITCH DOOR PC/ABS: Add texture free areas, Balance change w/ bottom housing (59-00353), Rev goes to C.

texture free areas, Balance change w/ bottom housing 11-059-00034 -- CVR DS200 PEB DOOR PC/ABS; Add (59-00353), Rev goes to D.

01-059-00353 - HSG DS200 BOTTOM PC/ABS: Add texture free areas, Use up existing, Rev goes to D.

change w/ bottom housing (59-00353), Rev goes to B. Coating PC/ABS: Add texture free areas, Balance 31-059-00524 - CVR DS200 REAR w/BATT Hole EMI

Click here to enter text.

OBSOLETE PARTS

59-00029 - DS2, Cover, Front (47 in stock)

59-00034 - DS2, Door, PEB (693 in stock)

59-00030 - DS2, Door, Switch (597 in stock)

59-00353-02 -- DS2, Base Plastic, 1.3, No Feet (19 in stock)

59-00524-01 - DS2,Top Rear Housing (0 in stock)

59-00524 - DS2, TOP REAR HOUSING w/EMI, use up stock 2295 - DS2, DOOR, PEB, use up stock 59-00353-01 - DS2, BASE PLASTIC, 1.3, NO FEET, use up 2316 - DS2, COVER, FRONT, use up stock 2244 - DS2, DOOR, SWITCH, use up stock

59-00524-01 - DS2, Top Rear Housing, ES&S procures 59-00353-02 -DS2, Base Plastic, 1.3, No Feet, ES&S 59-00029 - DS2, Cover, Front, ES&S procures 59-00030 - DS2, Door, Switch ES&S procures 59-00034 - DS2, Door, PEB ES&S procures procures

Include the part number, title, and disposition

Include the part number, title, who is procuring the part. **NEW PARTS**

Click here to enter text.



Engineering Change Order

	Click here to enter text.	r text.	<u>U</u>	lick here	Click here to enter text.		
CORRECTIONS Drawing changes that are not related to any part changes listed above.		ž					
QUALITY Vince Wingate V Approve I Ignore	nore	FIELD SERVICES Al Moraczewski Approve	Ignore		FULFILLMENT Lee McDermott V Approve	- Ignore	
PRODUCT MANAGEMENT Mike Dvorak ▼ Approve	nore	CERTIFICATION Sue McKay V Approve	Ignore		MATERIAL MANAGEMENT Stan Allen	MENT	110000000000000000000000000000000000000
SUSTAINING ENGINEERING Derek Caviness 7 Approve	nore	PRODUCT LINE ENGINEER Derek Caviness ▼ Approve	NEER Ignore		Dir. of Hardware Engineering Kevin Liesner	neering 	