



Registers

A	00	S	0
BC	00 00	Z	0
DE	00 00	AC	0
HL	00 00	P	0
PSW	00 00	C	0
PC	00 00		
SP	00 00		
Int-Reg	00		

Flag

Decimal - Hex Conversion

Decimal	Hex
0	0
→ To Hex	← To Dec

I/O Ports

0	-	0
Update Port Value		

Memory

0	-	0
Update Memory		

Load me at

```
1 LDA 8501
2 MOV B,A
3
4 LDA 8500
5 MVI C,00H
6
7 LOOP: CMP B
8 JC LOOP1
9
10 SUB B
11 INR C
12 JMP LOOP
13
14 LOOP1: STA 8503
15 MOV A,C
16 STA 8502
17
18 HLT
```

Data Stack KeyPad Memory I/O Ports

Start 8050

OK

Address (Hex) Address Data

1F72	8050	2
1F73	8051	20
1F74	8052	0
1F75	8053	0
1F76	8054	0
1F77	8055	0
1F78	8056	0
1F79	8057	0
1F7A	8058	0
1F7B	8059	0
1F7C	8060	0
1F7D	8061	0

Line No Assembler Message

0 Program assembled successfully

GNUSim8085 - 8085 Microprocessor Simulator

File Reset Assembler Debug Help



Registers

A	00	S	0
BC	00 00	Z	0
DE	00 00	AC	0
HL	00 00	P	0
PSW	00 00	C	0
PC	00 00		
SP	00 00		
Int-Reg	00		

Flag

Load me at

```

1 LDA 8501
2 MOV B,A
3
4 LDA 8500
5 MVI C,00H
6
7 LOOP: CMP B
8 JC LOOP1
9
10 SUB B
11 INR C
12 JMP LOOP
13
14 LOOP1: STA 8503
15 MOV A,C
16 STA 8502
17
18 HLT

```

Decimal - Hex Conversion

Decimal Hex

0 0

→ To Hex ← To Dec

I/O Ports

0 - + 0

Update Port Value

Memory

0 - + 0

Update Memory

Data Stack KeyPad Memory I/O Ports

Start 8502 OK

Address (Hex)	Address	Data
2136	8502	10
2137	8503	2
2138	8504	0
2139	8505	0
213A	8506	0
213B	8507	0
213C	8508	0
213D	8509	0
213E	8510	0
213F	8511	0
2140	8512	0
2141	8513	0

Line No Assembler Message

0 Program assembled successfully

Simulator: Idle