

Open-loop Transfer Function $L(s) = C(s)G(s)$:

$L =$

$$\frac{5s + 100}{0.005s^2 + 0.5s}$$

Continuous-time transfer function.

[Model Properties](#)

Closed-loop Transfer Function $T(s)$:

$T =$

$$\frac{5s + 100}{0.005s^2 + 5.5s + 100}$$

Continuous-time transfer function.

[Model Properties](#)


----- Stability Margins -----

Gain Margin = Infinite


Phase Margin = 94.59 degrees

Gain Crossover Frequency = 995.1904 rad/s

Phase Crossover Frequency = NaN rad/s



Bode Plot of Open-Loop System



Closed-Loop Step Response

