THREAD/SCREW - Drill & Tap Chart

I TREAD/SCREW - DITH & Tap Chart												
Machine Screw Size						Drills		Clearance Hole Drills				
				Alum, Brass, & Plasitcs		Stainless Steel, Steels & Iron		All Materials				
		Threads Per Inch		75% Thread		50% Thread		Close Fit		Free Fit		
# or Dia	Major Dia			Drill Size	Decimal Equiv.	Drill Size	Decimal Equiv.	Drill Size	Decimal Equiv.	Drill Size	Decimal Equiv.	
0	.0600	80	.0447	3/64	.0469	55	.0520	52	.0635	50	.0700	
1	.0730	64	.0538	53	.0595	1/16	.0625	48	.0760	46	.0810	
		72	.0560	53	.0595	52	.0635					
2	.0860	56	.0641	50	.0700	49	.0730	43	.0890	41	.0960	
		64	.0668	50	.0700	48	.0760					
3	.0990	48	.0734	47	.0785	44	.0860	37	.1040	35	.1100	
		56	.0771	45	.0820	43	.0890					
4	.1120	40	.0813	43	.0890	41	.0960	32	.1160	30	.1285	
		48	.0864	42	.0935	40	.0980					
5	.125	40	.0943	38	.1015	7/64	.1094	30	.1285	29	.1360	
		44	.0971	37	.1040	35	.1100					
6	.138	32	.0997	36	.1065	32	.1160	27	.1440	25	.1495	
		40	.1073	33	.1130	31	.1200					
8	.1640	32	.1257	29	.1360	27	.1440	18	.1695	16	.1770	
		36	.1299	29	.1360	26	.1470					
10	.1900	24	.1389	25	.1495	20	.1610	9	.1960	7	.2010	
		32	.1517	21	.1590	18	.1695					
		24	.1649	16	.1770	12	.1890					
12	.2160	28	.1722	14	.1820	10	.1935	2	.2210	1	.2280	
		32	.1777	13	.1850	9	.1960					
1/4	.2500	20	.1887		.2010	7/32	.2188	F	.2570	н	.2660	
		28	.2062	3	.2130	1	.2280					
		32	.2117	7/32	.2188	1	.2280					
5/16	.3125	18	.2443	F	.2570	J	.2770	Р	.3230	Q	.3320	
		24	.2614	I	.2720	9/32	.2812					
		32	.2742	9/32	.2812	L	.2900					
3/8	.3750	16	.2983	5/16	.3125	Q	.3320	W	.3860	×	.3970	
		24	.3239	Q	.3320	S	.3480					
		32	.3367	11/32	.3438	T	.3580					
7/16	.4375	14	.3499	U	.3680	25/64	.3906	29/64	.4531	15/32	.4687	
		20	.3762	25/64	.3906	13/32	.4062					
igwdown		28	.3937	Y	.4040	Z	.4130					
1/2	.5000	13	.4056	27/64	.4219	29/64	.4531	33/64	.5156	17/32	.5312	
		20	.4387	29/64	.4531	15/32	.4688					
		28	.4562	15/32	.4688	15/32	.4688					
9/16	.5625	12	.4603	31/64	.4844	33/64	.5156		.5781	19/32	.5938	
		18	.4943	33/64	.5156	17/32	.5312	37/64				
	I	I I		ı	I	I	I	I	I	I	1	

		24	.5114	33/64	.5156	17/32	.5312				
5/8	.6250	11	.5135	17/32	.5312	9/16	.5625	41/64	.6406	21/32	.6562
		18	.5568	37/64	.5781	19/32	.5938				
		24	.5739	37/64	.5781	19/32	.5938				
11/16	.6875	24	.6364	41/64	.6406	21/32	.6562	45/64	.7031	23/32	.6562
3/4	.7500	10	.6273	21/32	.6562	11/16	.6875	49/64	.7656	25/32	.7812
		16	.6733	11/16	.6875	45/64	.7031				
		20	.6887	45/64	.7031	23/32	.7188				
13/16	.8125	20	.7512	49/64	.7656	25/32	.7812	53/64	.8281	27/32	.8438
7/8	.8750	9	.7387	49/64	.7656	51/64	.7969	57/64	.8906	29/32	.9062
		14	.7874	13/16	.8125	53/64	.8281				
		20	.8137	53/64	.8281	27/32	.8438				
15/16	.9375	20	.8762	57/64	.8906	29/32	.9062	61/64	.9531	31/32	.9688
1	1.000	8	.8466	7/8	.8750	59/64	.9219	1-1/64	1.0156	1-1/32	1.0313
		12	.8978	15/16	.9375	61/64	.9531				
		20	.9387	61/64	.9531	31/32	.9688				

Steven L Henderson's Cutting Edge Designs