
ADVANTEST®**ADVANTEST CORPORATION**

ASX/U-51

SYSTEST TESTUTL ATLworks

UPDATE NOTICE

REV 6.03-1

MANUAL NUMBER 8262527-59

Applicable Products

PASX51-93****
PASX51-92****
PASX51-91****
PASX51-85****
PASX51-81****
PASX51-77****
PASX51-75****
PASX51-71****
PASX51-70****
PASX51-36****

PREFACE

ADVANTEST, ADVANsite, ATLworks and ATL are trademarks of ADVANTEST Corporation.

Sun, Sun Microsystems, the Sun Logo, SunOS and Solaris are trademarks or registered trademarks of Sun Microsystems, Inc. in the United States and other countries.

All other marks referenced herein are trademarks or registered trademarks of their respective owners.

RECORD OF REVISIONS

Manual Rev	Date	Remarks (Software REV)	Manual Rev	Date	Remarks (Software REV)
56	Mar 7/03	(REV 6.01)			
57	May 15/03	(REV 6.02)			
58	Jul 25/03	(Obsolete)			
58a	Sep 22/03	(REV 6.03)			
59	Oct 30/03	(REV 6.03-1)			

TABLE OF CONTENTS

1. SUMMARY OF REVISION	1-1
2. IMPROVED ITEMS	2-1
2.1 Tester Driver Controller	2-1
2.1.1 STOP MPAT, TIME LIMIT, and WAIT MPAT Statements	2-1
2.2 Tester Utility Program	2-1
2.2.1 /STHAND (Controlling the Handler by using the GPIB Interface)	2-1

1. SUMMARY OF REVISION

- (1) Revision number
 - ASX/U-51 REV 6.03-1
- (2) Applicable systems
 - T5593
 - T5592
 - T5591/T5591R
 - T5586/T5585
 - T5581/T5581H
 - T5581P/T5571P
 - T5377
 - T5376/T5375
 - T5371
 - T5336/T5311
- (3) Related manual revised

• ATL-51 TEST PLAN PROGRAM REFERENCE MANUAL	8431498-06
• ATL-51 SOCKET PROGRAM REFERENCE MANUAL	8256293-21
- (4) Reason of revision
 - Improvement of functions

1. SUMMARY OF REVISION

(5) Products revised

Products revised in this revision are shown below:

Product code	Product name		
PASX51-93****	SYSTEST51SU	TESTUTL51SU	ATW51SU
PASX51-92****			
PASX51-91****			
PASX51-85****			
PASX51-81****			
PASX51-77****			
PASX51-75****			
PASX51-71****			
PASX51-70****			
PASX51-36****			

ASX/U-51 SYSTEST TESTUTL ATLworks UPDATE NOTICE REV 6.03-1

1. SUMMARY OF REVISION

(6) List of revisions

The revision list shows the revision correspondence of the basic software the SYSTEST51SU, TESTUTL51SU and ATW51SU of ASX/U-51.

<Explanation of the revisions' list>

- (a) “*” shows the product revised in the revision.
- (b) “–” shows the product that does not exist to the whole revision.

ASX/U-51				
ASX/U-51 Overall Revision	Revision for each product			SunOS Revision
	SYSTEST51SU	TESTUTL51SU	ATW51SU	
5.04A	5.04A *	5.04A *	–	Solaris 2.5.1 Solaris 7
5.04A1	5.04A1 *	5.04A1 *	–	Solaris 2.5.1 Solaris 7
5.04A2	5.04A2 *	5.04A1	–	Solaris 2.5.1 Solaris 7
5.04A3	5.04A3 *	5.04A1	–	Solaris 2.5.1 Solaris 7
5.04A4	5.04A4 *	5.04A2 *	–	Solaris 2.5.1 Solaris 7
5.05(Note1)	5.05 *	5.05 *	5.05 *	Solaris 8
6.00	6.00 *	6.00 *	6.00 *	Solaris 2.5.1 Solaris 7 Solaris 8
6.00-1	6.00-1 *	6.00-1 *	6.00-1 *	Solaris 2.5.1 Solaris 7 Solaris 8
6.00-2	6.00-2 *	6.00-1	6.00-1	Solaris 2.5.1 Solaris 7 Solaris 8
6.00A	6.00A *	6.00A *	6.00A *	Solaris 2.5.1 Solaris 7 Solaris 8
6.00A1	6.00A1 *	6.00A1 *	6.00A	Solaris 2.5.1 Solaris 7 Solaris 8

ASX/U-51 SYSTEST TESTUTL ATLworks UPDATE NOTICE REV 6.03-1

1. SUMMARY OF REVISION

ASX/U-51				
ASX/U-51 Overall Revision	Revision for each product			SunOS Revision
	SYSTEST51SU	TESTUTL51SU	ATW51SU	
6.00B	6.00B *	6.00B *	6.00B *	Solaris 2.5.1 Solaris 7 Solaris 8
6.00C	6.00C *	6.00C *	6.00C *	Solaris 2.5.1 Solaris 7 Solaris 8
6.00C1	6.00C1 *	6.00C1 *	6.00C	Solaris 2.5.1 Solaris 7 Solaris 8
6.01(Note2)	6.01 *	6.01 *	6.01 *	Solaris 8
6.02	6.02 *	6.02 *	6.02 *	Solaris 2.5.1 Solaris 7 Solaris 8
6.03	6.03 *	6.03 *	6.03 *	Solaris 2.5.1 Solaris 7 Solaris 8
6.03-1	6.03-1 *	6.03-1 *	6.03-1 *	Solaris 2.5.1 Solaris 7 Solaris 8

Note1: REV 5.05 is used for the T5375.

Note2: REV 6.01 is used for the T5593.

2. IMPROVED ITEMS

2.1 Tester Driver Controller

2.1.1 STOP MPAT, TIME LIMIT, and WAIT MPAT Statements

If the STOP MPAT, TIME LIMIT, or WAIT MPAT statement was executed, the pattern generation, which used the match flag sense instruction, did not stop and the subsequent tests could not be conducted.

Improvement ➡ The pattern generation stops.

Relevant revisions: REV 6.00 through REV 6.03

Relevant test system: T5371

2.2 Tester Utility Program

2.2.1 /STHAND (Controlling the Handler by using the GPIB Interface)

If DISABLE was set to both test stations by using the /STHAND command and the Manual Start request was issued, the program did not start even if SDUT=0 was encountered.

Improvement ➡ The program starts when SDUT=0 is encountered.

Relevant revisions: REV 5.03 through REV 6.03

Relevant test systems: T5593, T5592, T5591, T5591R, T5586, T5585, T5581, T5581H, T5581P, T5571P, T5377, T5376, T5375, and T5371