







PCB total thickness is 1.6mm


CB material:FR-4

Single ended 50 Q	Differential 90 Ω		





Clearance Check	False	error	:0002		JOB NAME	NUCAM T	VP_162
Connectivity Check	False	error	:0000	Gao-Fu Technology Corp. http://www.gaofu.com.tw	LAYER	DARTWOR	K-¥TOP
Plane Check	False	error	:0000		DATE	105.06.16	4LAYER-A4





Clearance Check	False	error	:0002		JOB NAME	NUCAM T	VP_162
Connectivity Check	False	error	:0000	Gao-Fu Technology Corp. http://www.agofu.com.tw	LAYER	ARTWORK#1	BOTTOMIS
Plane Check	False	error	:0000		DATE	105.06.16	4LAYER-A4










CB total thickness is 1.6mm

PCB_material:FR-4

Single ended 50 Q	Different		



Clearance Check	False erro	:0002		JOB NAME	NUCAM TVP_162
Connectivity Check	False erro	:0000	Gao-Fu Technology Corp. http://www.gaofu.com.tw	LAYER	ARTAWDWORKS TOOMIS
Plane Check	False erro	:0000	886-3-6682475	DATE	105.06.16 4LAYER-A4