Report Generated by Test Manager

Title: **Automation Simulink Test**
Author: **Sung Hyun Park**
Date: **08-Dec-2023 14:39:21**

Test Environment

Platform: PCWIN64
MATLAB: (R2023b)

Summary

Name	Outcome	Duration (Seconds)
[Results: 2023-Dec-08 14:39:14](#)	2 ❌	4.492
🗔 [Simulink_TestManager](#)	❌	3.301
📁 [New Test Suite 1](#)	❌	3.301
📄 [New Test Case 1](#)	❌	3.301
🗔 [Simulink_TestManager](#)	❌	0.274
📁 [New Test Suite 1](#)	❌	0.275
📄 [New Test Case 1](#)	❌	0.274

Results: 2023-Dec-08 14:39:14

Result Type: Result Set
Parent: None
Start Time: 2023-12-08 14:39:15
End Time: 2023-12-08 14:39:20
Outcome: Total: 2, Failed: 2

Back to Report Summary

Simulink_TestManager

Test Result Information

Result Type: Test File Result
Parent: Results: 2023-Dec-08 14:39:14
Start Time: 2023-12-08 14:39:15
End Time: 2023-12-08 14:39:19
Outcome: Total: 1, Failed: 1

Test Suite Information

Name: Simulink_TestManager

Back to Report Summary

New Test Suite 1

Test Result Information

Result Type: Test Suite Result
Parent: Simulink_TestManager
Start Time: 2023-12-08 14:39:15
End Time: 2023-12-08 14:39:19
Outcome: Total: 1, Failed: 1

Test Suite Information

Name: New Test Suite 1

Back to Report Summary

New Test Case 1

Test Result Information

Result Type:	Test Case Result
Parent:	[New Test Suite 1](#)
Start Time:	2023-12-08 14:39:15
End Time:	2023-12-08 14:39:19
Outcome:	Failed
Cause of Failure:	Errors running test case

Test Case Information

Name:	New Test Case 1
Type:	Baseline Test

Simulation

System Under Test Information

Model:	Example
Release:	Current
Simulation Mode:	normal
Override SIL or PIL Mode:	0
External Input Name:	Test_Input2.mat
External Input File:	C:\ProgramData\Jenkins\.jenkins\workspace\Simulink_Test_ALL_Script\Test_Input2.mat
Start Time:	0
Stop Time:	0
Simulation Start Time:	
Simulation Stop Time:	

Simulation Error:
모델 '[Example](#)'을(를) 컴파일하지 못했습니다. 캐시된 결과가 불완전할 수 있습니다.

'[TCU/Chart](#)'에서 파라미터 '[Aps_val1](#)'에 대한 설정이 유효하지 않습니다.

Error evaluating Stateflow parameter data 'Aps_val1' in its parent workspace.

'Aps_val1'은(는) 인식할 수 없는 함수 또는 변수입니다.

Variable 'Aps_val1' does not exist.

"OverridesStruct"은(는) 인식할 수 없는 필드 이름입니다.

Simulink_TestManager

Test Result Information

Result Type:	Test File Result
Parent:	Results: 2023-Dec-08 14:39:14
Start Time:	2023-12-08 14:39:19
End Time:	2023-12-08 14:39:20
Outcome:	Total: 1, Failed: 1

Test Suite Information

Name:	Simulink_TestManager

New Test Suite 1

Test Result Information

Result Type:	Test Suite Result
Parent:	Simulink_TestManager
Start Time:	2023-12-08 14:39:19
End Time:	2023-12-08 14:39:20
Outcome:	Total: 1, Failed: 1

Test Suite Information

Name: New Test Suite 1

[Back to Report Summary](#)

New Test Case 1

Test Result Information

Result Type: Test Case Result
Parent: [New Test Suite 1](#)
Start Time: 2023-12-08 14:39:19
End Time: 2023-12-08 14:39:20
Outcome: Failed
Cause of Failure: Errors running test case

Test Case Information

Name: New Test Case 1
Type: Baseline Test

Simulation

System Under Test Information

Model: Example
Release: Current
Simulation Mode: normal
Override SIL or PIL Mode: 0
External Input Name: Test_Input2.mat
External Input File: C:\Users\Administrator\MATLAB\Projects\Simulink_Test\Test_Input2.mat
Start Time: 0
Stop Time: 0
Simulation Start Time:
Simulation Stop Time:

Simulation Error:
모델 '[Example](#)'을(를) 컴파일하지 못했습니다. 캐시된 결과가 불완전할 수 있습니다.

'TCU/Chart'에서 파라미터 'Aps_val1'에 대한 설정이 유효하지 않습니다.

Error evaluating Stateflow parameter data 'Aps_val1' in its parent workspace.

'Aps_val1'은(는) 인식할 수 없는 함수 또는 변수입니다.

Variable 'Aps_val1' does not exist.

"OverridesStruct"은(는) 인식할 수 없는 필드 이름입니다.