

#### DRIVER INSTALLATION GUIDE

The OptoForce DAQ requires a device driver in order to operate.

Operation systems like Windows 7 or Windows 8 may install it automatically.

However, in many cases the DAQ needs manual driver installation.

PLEASE NOTE THAT ADMINISTRATOR PRIVILAGE COULD BE REQUIRED FOR THE DRIVER INSTALLATION IF SO PLEASE CONTACT YOUR SYSTEM ADMINISTRATOR!

#### How to decide if manual installation is needed

#### **First Step**


Connect the sensor to the DAQ and to your PC, as it is shown in the figure below.

#### **Second Step**

In the pendrive, locate the *ODV* folder and start the OptoForce Data Visualization Software ( *OptoForce\_DV.exe* )

#### Result


If in the **OptoForce Data Visualization** software on the **Connection** tab, the **Available Sensors** shows **0** than manual driver installation is needed!





# WINDOWS VISTA & 7


- Please disconnect and reconnect the DAQ while the data visualization software is running to verify the automatic driver installation.
- If in the OptoForce Data Visualization software on the Connection tab, the Available
   Sensors shows 0 than manual driver installation may be needed.






- In order to do a manual driver installation the *Device Manager* must be opened.
- First make sure you have closed all running applications.
- Open the **START** menu and type in **devmgmt.msc** and hit **ENTER**.

PLEASE NOTE THAT ADMINISTRATOR PRIVILAGE COULD BE REQUIRED FOR THE DRIVER INSTALLATION IF SO PLEASE CONTACT YOUR SYSTEM ADMINISTRATOR!






In the Device Manager select OptoForce DAQ (with a small yellow triangle) and right-click
on that.






• From the pop-up menu choose **Update Driver Software...** .






• Then select Browse my computer for driver software.






• Hit Browse and point to the DRIVER folder on the pen drive.






• Browse for the **DRIVER** folder in the pen drive and hit **OK**.






· Then click on the Next button.






• Wait for the installation to complete.






- Once the installation completed a new USB Communication Port is available (that is required for the DAQ to communicate with the PC).
- You can close the dialog window.





- In case of a successful driver installation you must find a new USB Communication Port under the Ports (COM &LPT).
- Now **disconnect** the DAQ and then **reconnect** and you may **restart** your operating system.





- Now you can run the OptoForce Data Visualization Software and you can check the
   Available Sensors at the Connection tab to verify the success of the driver installation.
- For the first time you may disconnect and reconnect the DAQ (after the reconnect please wait for a few seconds.)
- If you can see available sensor(s) you are ready and you can start evaluating the development kit.

