


Twisted pairs with color-coded plastic insulation
Outer jacket



Twisted pairs with color-coded plastic insulation
Pair shields
Overall shield
Outer jacket
Shielded twisted pair



Foil Shield
Braided Shield
Center Conductor
Outer Jacket
Dielectric










Straight thru cable
X-over cable
TX+ 1
TX- 2
RX+ 3
4
5
RX- 6
7
8
1 RX+
2 RX-
3 TX+
4
5
6 TX-
7
8
TX+1
TX -2
RX+3
4
5
RX- 6
7
8
1 TX+
2 TX-
3 RX+
4
5
6 RX-
7
8
Here you can compare the different pinsouts between a straight thru and x-over cable. The Transmit and Receive pins are also shown


Straight through network cable: both sides should be A
Crossover cable: One side A, one side B
A
white/orange stripe
orange solid
white/green stripe
blue solid
white/blue stripe
green solid
white/brown stripe
brown solid
Clip underneath, pins facing you
B
white/green stripe
green solid
white/orange stripe
white/brown stripe
brown solid
orange solid
blue solid
white/blue stripe
Clip underneath, pins facing you


Clip underneath, pins facing you
orange solid
white/green stripe
blue solid
white/blue stripe
green solid
white/brown stripe
Clip underneath, pins facing you


A
B


A
orange solid
white/green stripe
blue solid


A
orange solid
white/green stripe
blue solid
white/blue stripe
underneath,


white/green stripe
green solid
white/orange stripe
white/brown stripe