Wilson II Printed parts guide

Belt-guide-624.stl (4)	
Extruder-direct-drive.stl	
Fanduct-e3dlite6.stl	
Filament-mount.stl	
Power-switch-mount.stl	
Psu-mount.stl (2)	

Ramps-mount.stl	
Servo-endstop-holder.stl	
Servo-mount.stl	
Smartlcd-mount.stl	
X-carriage.stl	

X-end-idler.stl	
X-end-motor.stl	
X-tensioner.stl	
Y-brace.stl (4)	
Y-idler.stl	

Y-motor.stl	
Y-table-10.stl	
Y-tensioner.stl	
Z-lower-brace-1.stl	
z-lower-brace-2.stl	

Z-motor-left.stl	
Z-motor-right.stl	
Z-top-left.stl	
Z-top-right.stl	